

PRIMARY CORNER DESCRIPTION Sec. Cor. for 29, 30, 31 and 32

Alias _____ Description _____
 Alias _____ Description _____
 Alias _____ Description _____
 Alias _____ Description _____

GLO survey by Harvey Gordon and Charles T. Gardner, Deputy Surveyors, under Contract #52 dated Feb. 17, 1855 (DCSO records Vol. 2 Page(s) 813)

 Set post cor. of secs. 29, 30, 31 and 32, from which
 A Fir 15" dia., bears S.17°W., 13 lks. dist.
 A Fir 12" dia., bears S.77°E., 40 lks. dist.
 A Fir 15" dia., bears N.58°E., 57 lks. dist.
 A Fir 20" dia., bears N.41°W., 41 lks. dist.

F.C. Frear, co. Roadmaster - Jan. 1924 - Co. Road #65

 Rock for section corner. (Bears S.69°37'E., 22.2 ft. from centerline of road)

Ronald W. VanDomelen - Feb. 1969 - M 37-72

 Found - 5" x 8" x 12" stone mkd. "S +31" on top and "NEC" on NE. face.
 3/4" Iron rod on NW. side of stone and rotted fence post on NE. side of stone.
 No bearing objects present.
 Marked for BTs:
 6" D.Fir bears N.24°E., 22.4 ft. mkd. CS BT.
 8" D.Fir bears N.89°E., 9.0 ft. mkd. CS BT.

Douglas County Surveyors Office - Vernon "Ray" Tracy and crew July 28, 1970 - C.S. File 54/14-49

 Found - 3/4" x 24" I.Rod set alongside old rock, mkd. "NEC" on NE. and "S +31" on top.
 Remains of Fir stump S.77°E., 26.4 ft. no scribe fd.
 Remains of Fir stump N.58°E. 37.6 ft., no scribe fd.
 8" D.Fir N.89°E., 9.0 ft. mkd. CS BT. (1969)
 6" D.Fir N.24°E., 22.4 ft. mkd. CS BT. (1969)

Set Brass cap at cor. mkd: County Surveyors Office
 (Reset rock & I.R. T 21 S R 5 W
 alongside brass cap) S 30 | S 29
 S 31 | S 32

1970

New BTs- 12" W.Fir S.4°E., 52.2 ft. mkd. T21S R5W S32 CSBT
 30" D.Fir N.52°W., 49.4 ft. mkd. T21S R5W S30 CSBT,
 (marked above fence, this BT across county road)
 A fence corner bears N.59°W., 10.0 ft., fences S.30°E and S.15°W.
 Centerline of Co. Road bears N.59°W., 27.0 ft.
 (Cont. Next Page)

TOWNSHIP 21 RANGE 05 POINT IDENTIFIER # 200200

PRIMARY CORNER DESCRIPTION Sec. Cor. for 29, 30, 31 and 32

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

The corner stone found at this corner was either found or set by Frear in 1924. We check the tie to the P.I. as made by Frear then, we do not believe the rock has been moved since that time. Also, the remnants of the old Fir stumps found are identical bearings and distances as those of the orig. govt. field notes. With this much evidence there at the time of our visit, we believe this to be the location of the orig. corner.

BLM resurvey by Wayne L. Rogers, Cadastral Surveyor, Group #1059, surveyed April/Dec. 1981 - (DCSO records Vol. 45 Page(s) 17320-21)

The Sec. Cor., perpetuated and recorded by Frear in 1924, further perpetuated and recorded by VanDomelen in 1969, and still further perpetuated and recorded by Tracy in 1970, monumented with an iron post, 1 1/4" dia., firmly set, projecting 10" above ground with brass cap mkd. in 1970, from which the remains of the original bearing trees:

A root hole bears N.58°E., 57 lks. dist.

A decayed Fir stump, size indeterminate, bears S.77°E., 40 lks. dist., no marks visible.

and bearing trees mkd. by VanDomelen:

A Fir 12" dia., bears N.29°E., 35 lks. dist., with healed blaze.

A Fir 15" dia., bears N.77 3/4°E., 14 lks. dist., with healed blaze.

and bearing trees mkd. by Tracy:

A Grand Fir 20" dia., bears S.4°E., 79 lks. dist., with healed blaze.

A Fir 32" dia., bears N.52°W., 74 lks. dist., with healed blaze.

and a new bearing object:

A Power Pole No. 7B-35 1, bears S.63 1/4°W., 151 lks. dist.

Fd. OK, Aug. 1990 - M 110-52

Fd. OK March 1991 - M 111-71

Fd. OK, Nov. 20, 1991, DCSO - C.S. File 64/21-9

Fd. OK, Nov. 1997 by Hendricks - 1998-0007

Fd. OK by Carl Sweeden, 12/2005 - M149-19

Fd. Ok by Carl Sweeden, 12/2006 - 2007-0006