

TOWNSHIP 21 RANGE 05 POINT IDENTIFIER # 200240

PRIMARY CORNER DESCRIPTION 1/4 cor. for Secs. 29 and 30

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GL0 survey by Harvey Gordon and Charles T. Gardner, Deputy Surveyors, under Contract #52 dated Feb. 17, 1855 (DCSO records Vol. 2 Page(s) 814)

Set ¼ sec. post, from which
A Fir 79" dia., bears N.56°E., 31 lks. dist.
A Fir 18" dia., bears N.72°W., 36 lks. dist.

A.R. Evans - Wit: Clinton Woolley - Feb. 25, 1952 - C.S. File 41/5

Found stump of old BT, 80" Fir N.56°E., 31 lks.
Set 1/2" Iron pipe for corner.
Blazed and scribed BTs:
54" Fir N.10°W., 68.0 ft. mkd. ¼ S30 R.E. 2741 BT.
6" Laurel S.52½°E., 24.0 ft. mkd. ¼ S29 R.E. 2741 BT.

Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy - Stoffel and Stone, crew - Dec. 1964 - C.S. File 49/68-47

Found - 1/2" Iron pipe.
54" Fir stump, N.10°W., 68.0 ft., bark scribing plainly visible.
10" Madrone S.52½°E., 24.0 ft., bark scribed.
Badly rotted large Fir stump N.56°E., 20.5 ft., no marks visible.
Blaze and Rescribe:
10" Madrone S.52½°E., 24.0 ft. mkd. "¼ S29 CS BT"
New BT - 11" D.Fir N.41°W., 182.2 ft. mkd. "¼ S30 CS BT"
Corner is in N. & S. fence line.

BLM resurvey by Wayne L. Rogers, Cadastral Surveyor, Group #1059, surveyed April/Dec. 1981 - (DCSO records Vol. 45 Page(s) 17322)

The ¼ sec. cor., perpetuated and recorded by Evans, in 1952, and further perpetuated and recorded by Godfrey in 1964, monumented with an iron pipe, 1/2" dia., firmly set, projecting 4" above ground, from which the remains of an original bearing tree
A sawed Fir stump 80" dia., bears N.56°E., 31 lks. dist., with axe marks visible on bark.
and the remains of bearing trees mkd. by Evans:
A Madrone 12" dia., bears S.54°E., 36 lks. dist., with healed double blaze.
A sawed Fir stump 54" dia., bears N.13°W., 103 lks. dist., with scribe marks RE 27 ¼ S30 BT visible on bark blaze.
(Cont. Next Page)

TOWNSHIP 21 RANGE 05 POINT IDENTIFIER # 200240

PRIMARY CORNER DESCRIPTION 1/4 cor. for Secs. 29 and 30

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

and a bearing tree mkd. by Godfrey:
A Fir 14" dia., bears N.39 3/4°W., 277 lks. dist., with
healed double blaze.
At the corner point
Set an iron post, 28" long, 2 1/2" dia., 24" in the ground,
with brass cap mkd: T 21 S R 5 W
1/4
S 30 | S 29
1981
Reset the iron pipe alongside the iron post.
Corner is located at intersection of wire fences, extending
generally N., S., and E.

Fd. OK, March 1991 - M 111-71

Harvey Christensen - For: Seneca Jones Timber Co. - May 2007
- M153-23

Found - 2.5" BLM 1981 BC stamped "1/4 S30 S29 1981" 0.3 ft.
above grade.
18" P. Madrone S.54°E., 23.8 ft. healed face.
NW BT missing
Note - No suitable trees to North East.