

PRIMARY CORNER DESCRIPTION Sec. Cor. for 19, 20, 29 and 30

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by Harvey Gordon and Charles T. Gardner, Deputy Surveyors, under Contract #52 dated Feb. 17, 1855 (DCSO records Vol. 2 Page(s) 814)

-----  
Set post cor. of secs. 19, 20, 29 and 30, from which  
A Fir 10" dia., bears N.25°W., 12 lks. dist.  
A Fir 8" dia., bears N.23°E., 29 lks. dist.  
A Fir 6" dia., bears S.80°E., 28 lks. dist.  
A Fir 10" dia., bears S.60°W., 44 lks. dist.

GLO survey by W.H. Byars, Deputy Surveyor, under Contract #152, dated June 3, 1871, - (DCSO records Vol. 2 Page(s) 815)

-----  
The cor. and witness trees to secs. 19, 20, 29 and 30 being destroyed Set post cor. to secs. 19, 20, 29 and 30, from which  
A Fir stub, 24" dia., bears N.15°E., 82 lks. dist.  
A Fir stub, 30" dia., bears S.63°E., 150 lks. dist.  
A Fir stub, 30" dia., bears S.38°W., 48 lks. dist.  
A Fir stub, 36" dia., bears N.18°W., 70 lks. dist.

GLO survey by D.W. Applegate, under Contract #351, dated May 11, 1880 - (DCSO records Vol. 2 Page(s) 816)

-----  
Found the cor. of sec. 19, 20, 29 and 30 entirely obliterated by fire. Re-established the cor. of secs. 19, 20, 29 and 30, by setting a stone, 2 ft. x 6 x 8" with trench, etc. No bearing trees in reach. Found the description of country to correspond with notes furnished by Surveyor General.

GLO survey by W. P. Wright, U.S. Deputy Surveyor, under Contract #514, dated August 27, 1884 (DCSO records Vol. 2 Page(s) 824)

-----  
The Sec. Cor., which is a post 6" dia., in ground, mkd. T21S S20 on NE.; R5W S29 on SE.; S30 on SW.; S19 on NW. face, with 5 notches on E. and 2 on S. edge, from which  
A Fir 30" dia., bears N.23°E., 29 lks. dist. mkd. T21S R5W S20 BT.  
No more bearing trees.

O.F. Thiel - For: Perkins and Bridges - March 19, 1903 - C.S. File 64/48 Pg. 15

-----  
Stone set in ground, dead Cedar bears N.65°E., 1.38. Dead Fir fallen with marks.

(Cont. Next Page)

Alias \_\_\_\_\_ Description \_\_\_\_\_  
 Alias \_\_\_\_\_ Description \_\_\_\_\_  
 Alias \_\_\_\_\_ Description \_\_\_\_\_  
 Alias \_\_\_\_\_ Description \_\_\_\_\_

A.R. Evans - Wit: Clinton - Feb. 1952- C.S. File 41/5

-----  
 Found rock with cross per govt. field notes.  
 Blazed and scribed BT:  
 12" Fir S.52°E., 150.4 ft. mkd. T21S R5W S29 R.E. 2741 BT.  
 (Only tree available.)

Douglas County Surveyors Office - Vernon "Ray" Tracy and crew  
 Dec. 8, 1970 - C.S. File 54/14-47

-----  
 Found - Corner stone mkd. "+" on top with 3 notches on S.  
 and 1 notch on W. and BT as called for by Evans.  
 12" now 15" Fir, decayed sawed stump, S.2°E., 150.4  
 ft., we open lower blaze and find "BT" scribe and  
 reverse. (See note below)

Set Brass cap at cor. mkd: County Surveyors Office  
 (Reset old Cor. stone T 21 S R 5 W  
 alongside) S 19 | S 20

S 30 | S 29  
 1970

New BTs- 8" D.Fir S.1°E., 232.2 ft. mkd. T21S R5W S29 CS BT.  
 14" Apple S.59°W., 135.8 ft. mkd. T21S R5W S30 CSBT  
 Power Pole #7C-48/2 bears N.28°W., 104.2 ft.

This corner lies in old N-S fence line.

Note: When A.R. Evans renewal was recorded in book, the brg.  
 should have read S.2°E., not S.52°E. Using correct brg., we  
 found the stone Evan's called for and decayed remnants of  
 scribed wooden post. We defaced BTs previously mkd. and  
 RESET brass cap at proper point.

Douglas Co. Surveyors Office - Randall Smith and Stephen  
 Flause, crew - Oct. 29, 1991 - C.S. File 64/21-2

-----  
 Found - 1970 DCSO brass cap on a 1¼" O.D. Iron pipe  
 protrudes 7" above ground.

A Stone measuring 8" x 6" protruding 5" above ground  
 is found along East side of BC/IP. No marks  
 visible (Rec. 2 ft. x 6 x 8" (1880 survey)

12" now rotted D.Fir stump of indeterminable size  
 with illegible scribing visible, bears S.4°E.,  
 150.4 ft. (Rec. S.2°E., 150.4 ft. in 1970)

8" now 26" dia. D.Fir with a fully healed single  
 blaze bears S.3°E., 232.2 ft. (Rec. S.1°E., 232.2  
 ft.) (1970)

14" now 17" dia. Apple with a partially healed  
 single blaze, bears S.57°W., 135.8 ft. 9Rec.  
 S.59°W., 135.8 ft.)

(Cont. Next Page)

TOWNSHIP 21 RANGE 05 POINT IDENTIFIER # 200300

PRIMARY CORNER DESCRIPTION Sec. Cor. for 19, 20, 29 and 30

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Power Pole #7C-48 2, bears N.30°W., 104.2 ft. (Rec. N.28°W., 104.2 ft.)  
New BT - 36" dia. measured 1 ft. above ground, English Walnut, not blazed or scribed, bears N.59½°W., 174.8 ft.

BLM Resurvey by Bryan S. Seibold, Cadastral Surveyor, under Group #1564, Surveyed Aug/Nov. 1990 - (DCSO records Vol. 50 Page(s) 19053-54)

-----  
The Sec. Cor., perpetuated by Evans in 1952, further perpetuated by Tracy in 1970, monumented with an iron post 1¼" dia., firmly set, projecting 9" above ground, with brass cap mkd. in 1970, from which bearing trees and a bearing object mkd. by Tracy:  
A Fir 26" dia., bears S.1°E., 351 lks. dist., with fragmentary scribe marks visible on a bark blaze.  
An Apple 17" dia., bears S.59°W., 205½ lks. dist., with scribe marks T21S R5W S30 CS BT visible on open blaze.  
A power pole, 12 ins. diam., bears N.28½°W., 157½ lks. dist., No. 7C-48 2.  
and a new bearing object:  
A Power pole 12" dia., bears N.22°E., 368 lks. dist. No. 7C-48 1.  
The original corner stone monument is alongside the iron post.

Fd ok by G.Riley, 2/1998 - M128-26  
Fd ok by D.Edwards, 2/2001 - M136-67