

TOWNSHIP 21 RANGE 05 POINT IDENTIFIER # 200440

PRIMARY CORNER DESCRIPTION 1/4 Cor. for 17 and 18

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by W. P. Wright, U.S. Deputy Surveyor, under Contract #514, dated August 27, 1884 (DCSO records Vol. 2 Page(s) 827)

Set post 4" dia., 4 ft. long, with mkd. stone 12" in ground for ¼ sec. cor. mkd. ¼ S on W. face, from which
A Fir 24" dia., bears S.16°E., 30 lks. dist. mkd. ¼ S BT
A Cedar 12" dia., bears S.48°W., 49 lks. dist. mkd. ¼ S BT

Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy - Vernon Tracy; Clete Putnam, crew - March 1962 - C.S. File 49/89-49

Found - Rock mound at corner, no markings found on any rock. Rotted Fir snag, S.16°E., 19.8 ft. scribed "¼" visible on charred face, facing corner.
The Cedar BT to the SW. is down and impossible to tell just where it stood, however, it is approx. right dist. and brg., viz. S.48°W., 32.3 ft.
Rolled Cedar over and found good scribing "BT" on old face, was lying face down.

Set Brass cap at cor. mkd: County Surveyors Office
T 21 S R 5 W
¼ S18|S17
1962

New BTs- 20" D.Fir N.22°W., 8.6 ft. mkd. ¼ S18 CS BT.
15" R.Cedar N.82½°E., 24.6 ft. mkd. ¼ S17 CS BT.
Corner lies in bottom of canyon, approx. 10 ft. South of small stream flowing East.

Fd. OK, July 1989 by D. Peel - M 108-55