

TOWNSHIP 21 RANGE 05 POINT IDENTIFIER # 300100

PRIMARY CORNER DESCRIPTION Sec. Cor. for 32 & 33; 4 & 5 of T22-5

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GL0 survey by Gordon and Gardner, under Contract #52 dated Feb. 17, 1855 (DCSO records Vol. 2 Page(s) 792)

-----  
Set Post cor. of secs. 4, 5, 32 and 33, from which  
A Fir 12" dia., bears N.42°E., 17 lks. dist.  
A Fir 30" dia., bears N.57°W., 37 lks. dist.  
A B.Oak 10" dia., bears S.88°W., 49 lks. dist.  
A B.Oak 8" dia., bears S.62°E., 78 lks. dist.

J. Cole, Deputy - Wit: R.Haven; Geo Pasker - Oct. 18, 1915 - Vol. 3 Pg. 176; Field Book 64 Page 2

-----  
Renew cor. from remains of original trees. Set Oak post, from which  
Fir 30" dia., N.42°E., 11 ft.  
Fir 36" dia., S.69 3/4°E., 58 ft.  
Fir 24" dia., S.50½°W., 83 ft.  
Fir 16" dia., N.68°W., 45 ft.

Survey by J.W. Cole, County Surveyor - For: W.C. Sagaberd and J. Grimm - Jan. 1924 - Vol. 3 Pg. 176; Field book 52 Pg. 18

-----  
Found stake properly marked, also CS, from which  
A Fir BT marked and remarked, bears N.42°E., 11.0 ft.  
Stump 30" Fir N.57°W., 24 ft.  
Fir 30", S.70°E., 58 ft.  
Set Iron pipe 1½" x 40".  
(BTs previously remarked by Floyd J. Cole per J.W. Cole)

Douglas Co. Surveyors Office - James Byron, Deputy - Crew, Milo Godfrey; Clete Putnam - Aug. 19, 1959 - C.S. 49/59-32

-----  
Found - 12" now 40" Fir, N.42°E., 11.2 ft., shows good scribe, I do not open.  
Remains of rotted stump, checks bearing and distance for orig. NW BT.  
Fir snag, previously opened, shows good scribing, S.50½°W., 83.0 ft., Cole.  
Cole's N.69 3/4°E., 58.0 ft. BT, previously opened.  
I find 1" iron pipe at corner driven in 1½" iron pipe set by Cole.

I do not set brass cap at corner.

New BTs -9" R.Fir bears N.51°W., 18.0 ft. scribed T21S R5W S32 CS BT.  
6" R.Fir bears S.38½°W., 39.5 ft. T22S R5W S5 CS BT.  
8" R.Fir bears S.20°E., 31.0 ft. scribed T22S R5W S4 CS BT.

TOWNSHIP 21 RANGE 05 POINT IDENTIFIER # 300100

PRIMARY CORNER DESCRIPTION Sec. Cor. for 32 & 33; 4 & 5, T22-5

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Survey by Donald Peel - For: Weyerhaeuser Co. - Feb. 1992 - M 114-60

-----  
CONDITION REPORT ONLY.

Found - 3/4" Iron pipe.  
48" Fir N.41 3/4°E., 12.2 ft., closed face, BLM tag.  
17" Fir stump S.22 1/4°E., 31.0 ft, cut below scribing.  
15" Fir stump S.37 1/4°W., 39.1 ft, cut below scribing.  
17" Fir N.51 1/2°W., 17.7 ft., closed face.

Survey by Harvey Christensen - For: N.W. Timberland Cons. - Nov. 10, 1994 - M 121-21

-----  
Found - 1" O.D. iron pipe.  
50" D.Fir stump, N.42°E., 12.2 ft., healed face.  
17" D.Fir, N.52°W., 17.7 ft., healed face.  
15" D.Fir stump, (S.37°W. 39.1 ft.) missing.  
17" D.Fir stump, (S.22°E. 31 ft.) missing.  
Set 6 ft. fence post, 1 ft. West.

DCS0-GIS Corner visitation - 10/17/2005 - Typed: 1/14/2011 - C.S. File 67/33-1

-----  
Monument - 1" IP      Comment - stumps only

Douglas Co. Surveyors Office - Stephen J. Flause - Mike Koch - Garrett McGraw - 4/6/2011 - C.S. File 67/33-29

-----  
Found - A 1" inside dia., IP firmly and plumbly set protruding 6" above ground. 1959, unknown orig.  
1 1/2" iron pipe from 1924 is not seen, apparently deeply set.  
A fir, 12" dia., now a 44" dia., 2 ft. tall fir stump with possible healed blaze; bears N.42°E., 11.2 ft. (as per rec.) Orig  
A fir 30" dia., now a root-hole containing fir remnants (no marks fd); bears N.57°W., 24.4 ft. (as per rec.) Orig.  
A fir 36" dia., now a 60" dia., 3 ft. tall fir stump, no mark seen (face side buried under pack-rat nest which is not disturbed) bears S.71°E., 58.0 ft. (rec. S.69 3/4°E., 58 ft.) 1915  
A fir 16" dia., now a depression with fir roots; bears N.68°W., 45.0 ft. (as per rec) 1915  
A 9" fir, now an 18" DBH 6 ft. tall D.Fir stump with a fully healed double blaze; bears N.51°W., 18.0 ft. (as per rec.) 1959

continued next page

TOWNSHIP 21 RANGE 05 POINT IDENTIFIER # 300100

PRIMARY CORNER DESCRIPTION Sec. Cor. for 32 & 33; 4 & 5 of T22-5

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

New - A 7" DBH D.Fir scribed "T21S R5W S33 CS" "BT" on a double blaze; bears N.55°E., 16.1 ft.  
A 9" DBH Madrone scribed "T22S R5W S5 CS" "BT" on a double blaze; bears S.47°W., 88.7 ft.  
A 12" DBH D.Fir scribed "T22S R5W S5 CS" "BT" on a double blaze; bears S.77°W., 25.2 ft.  
An 8" DBH B.Oak scribed "T21S R5W S32 CS" "BT" on a double blaze; bears N.32°W., 5.5 ft.

Note - Monument is on NE edge of high reprod forested bench. Clear cut land slopes steeply to NE from here.  
Compass decl. 15¾°E.

Fd as per record, 3/2016 - M170-69 by R. Rice