

TOWNSHIP 21 RANGE 05 POINT IDENTIFIER # 340400

PRIMARY CORNER DESCRIPTION 1/4 cor. for Secs. 16 and 21

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Harvey Gordon and Charles T. Gardner, Deputy Surveyors, under Contract #52 dated Feb. 17, 1855 (DCSO records Vol. 2 Page(s) 811)

-----  
Set ¼ sec. post, from which  
A Fir 8" dia., bears N.20°W., 32 lks. dist.  
A Redwood 9" dia., bears S.11°W., 25 lks. dist.

Douglas County Surveyors Office - Vernon "Ray" Tracy and crew  
Aug/Sept. 1965 - C.S. File 54/14-6

-----  
Found - Badly burned Cedar BT as follows, Orig. 9" now 12"  
Cedar S.11°W., 16.5 ft., "BT" reverse scribe and  
partial face of upper scar.

No trace of other orig. BT.  
Set Brass cap at cor. mkd: County Surveyors Office  
T 21 S R 5 W  
¼ S 16  
S 21  
1965

New BTs- 18" D.Fir S.19°W., 38.5 ft. mkd. ¼ S21 CS BT.  
20" D.Fir N.78°E., 96.0 ft. mkd. ¼ S16 CS BT.  
Corner lies on West side of top of spur, ridge running S.W.

Fd. & used on BLM dependent resurvey by Wayne Rogers & Bryan Seibold Cadastral Surveyors & Robert Browning, Surveying Technician, under Group #1814, surveyed Aug. 1996/April 1998 - (DCSO rec. Vol. 53 Page(s) 20414)