

TOWNSHIP 21 RANGE 05 POINT IDENTIFIER # 400100

PRIMARY CORNER DESCRIPTION Sec. Cor. for 33 & 34; 3 & 4, T22-5

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Gordon and Gardner, under Contract #52 dated Feb. 17, 1855 (DCSO records Vol. 2 Page(s) 792)

Set post, cor. of secs. 3, 4, 33 and 34, from which
A Fir 30" dia., bears S.23°W., 174 lks. dist.
A Fir 36" dia., bears S.15°E., 256 lks. dist.
A Fir 24" dia., bears N.3½°E., 211 lks. dist.
A Fir 20" dia., bears N.80°W., 309 lks. dist.

B.B. Irving - J.S. Snyder; Elwood Nelson - June 17, 1938 - C.S. File 16/8 and also C.S. File 37/195

Identified from stump of O.B.T., S.15°E., 256 lks. Also O.B.T., N.80°W., 309 lks, not chopped out.
Set 2" x 48" I.P., 12" in ground in field, from which
O.B.T. 44" Fir, N.80°W., 205 ft., remarked.
12" Chinquapin N.10°E., 271.5 ft.
24" Fir N.40°W., 104.0 ft.
8" Alder S.30°E., 244.7 ft.

Arthur Boyer - J.S. Snyder; A. Boyer; Teashell and Wiley - Jan. 10, 1939 - C.S. File 16/8

Drove 1/2" x 36" long I.P., flush.

Lester E. Calder - For: Weyerhaeuser Co. - Dec. 1, 1960 - C.S. File 51/147-1 & C.S. File 53/105-A8 for Wilt report*

Found - 20" Fir N.80°W., 309 lks., now 44" Fir stump, scribing probably destroyed in logging. (Orig.) 1855 Post, SW.; SE.; and NE.; orig. BTs gone.
No trace of 2" I.P. from 1938.
No trace of 12" Chinquapin, N.10°E., 271.5 ft.
21" Fir N.40°W., 104.0 ft., now 24" Fir stump, scribed "BT".
44" Fir N.80°W., 205.0 ft. Orig. BT.
8" Alder S.30°E., 244.7 ft., now 10" and dead, scribing visible.
Set 1" x 30" alum. pipe for cor. using the two existing County BTs and the one orig. GLO BT.
Referenced by Wm. Wilt* (plates and "W" nails only)
6" Fir S.70°E., 82.2 ft.
4" I.Cedar S.37°E., 36.8 ft.
4" Fir S.78°W., 44.2 ft.
24" Fir stump N.46°W., 104.0 ft. CSBT.

(Cont. Next Page)

TOWNSHIP 21 RANGE 05 POINT IDENTIFIER # 400100

PRIMARY CORNER DESCRIPTION Sec. Cor. for 33 & 34; 3 & 4, T22-5

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy - Wm. Stoffel and Mike Stone, crew - Nov. 30 1964 - C.S. File 49/68-46

Found - 1" Alum. pipe set by Calder in 1960.
Stump of 24" D.Fir N.40°W., 104.0 ft., scribing still visible, "BT".
Rotten Fir stump S.15°E., 169.0 ft., no marks visible, orig. BT.
Stump of 8" Alder S.30°E., 244.7 ft., faces visible but scribing rotted away.
Stump of 4" I.Cedar S.37°E., 36.8 ft. (Calder's BT)
8" D.Fir, S.70°E., 82.2 ft. blazed and scribed "T22S R5W S3 CS BT"
8" D.Fir, S.78°W., 44.2 ft., blazed and scribed "T22S R5W S4 CS BT"
New BTs -8" D.Fir N.86°E., 57.2 ft. mkd: T21S R5W S34 CS BT.
8" D.Fir N.54°W., 34.6 ft. mkd: T21S R5W S33 CS BT.
Alum. pipe extends approx. 12" above ground.
DID NOT SET BRASS CAP.

Fd OK, Oct. 1988, David Wellman, M 107-26 & C.S. File 63/85-6
Fd. OK, Oct. 1995, D.Baker, M 119-77
Found OK by C. Sweeden, Oct. 2001 - M138-75

DCS0-GIS Corner visitation - 10/18/2005 - Typed: 1/18/2011 - C.S. File 67/33-1

Monument - 1" ID/IP comment - 2 love BTs

FD OK by N. Hibbs 3/2008 - M155-19
FD OK by N. Hibbs 12/2010 - M161-74