

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 21 & 22

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by Harvey Gordon and Charles T. Gardner, Deputy Surveyors, under Contract #52 dated Feb. 17, 1855 (DCSO records Vol. 2 Page(s) 807)

-----  
Set 1/4 sec. post, from which  
A Fir, 15" dia., bears N.45°E., 19 lks.  
A Redwood, 8" dia., bears N.85°W., 9 lks.

BLM dependent resurvey by Wayne Rogers & Bryan Seibold Cadastral Surveyors & Robert Browning, Surveying Technician, under Group #1814, surveyed Aug. 1996/April 1998 - (DCSO rec. Vol. 53 Page(s) 20409-10)

-----  
Point for the 1/4 sec. cor. of secs. 21 & 22, at proportionate dist., there is no remaining evidence of the original cor. Set a stainless steel post, 28" long, 2 1/2" diam., 26" in the ground, with brass cap mkd:

T21S R5W  
1/4  
S 21|S 22  
1996

from which  
A fir, 14" dia. bears N.50 3/4°E., 15 lks., mkd. 1/4 S22 BT.  
A fir, 11" dia., bears N.16 1/2°W., 39 lks., mkd. 1/4 S21 BT.  
Deposit a magnet in a white plastic case at the base of the stainless steel post.  
From this point, a point established by person(s) unknown, bears N.2°54'46"E., 1.363 chs., monumented with an iron pipe, 1/2" diam., badly bent, projecting 3" above ground. This point is improperly positioned, and was not used in this survey.

Harvey Christensen, For: Guistina Land & Timber and Thomas Mulder - Sept. 1999 - M 133-32

-----  
Found - 3.25" 1996 BLM flush with ground.  
14" D.Fir N.51°E., 10.0 ft. scribing visible.  
11" D.Fir N.16°W., 25.6 ft. scribing visible.  
0.5" I. Pipe N.3°E., 90.2 ft.  
18" D.Fir S.1°E., 22.8 ft. blazed & scribed "1/4 S22 BT"  
23" D.Fir S.88°W., 22.8 ft. blazed & scribed "1/4 S21 BT"