

PRIMARY CORNER DESCRIPTION 1/4 cor. for Secs. 3 and 4

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by W. P. Wright, U.S. Deputy Surveyor, under Contract #514, dated August 27, 1884 (DCSO records Vol. 2 Page(s) 821)

Set post 4" dia., 4 ft. long, with mkd. stone 12" in ground for ¼ sec. cor. mkd. ¼ S on W. face, from which
A Fir 10" dia., bears S.75°E., 33 lks. dist. mkd. ¼ S BT
A Fir 60" dia., bears N.47°W., 22 lks. dist. mkd. ¼ S BT

Douglas County Surveyors Office - Vernon "Ray" Tracy and crew July 1965 - C.S. File 54/14-18

Found - Orig. 10" now 19" Fir S.75°E., 21.8 ft., open and find scribe.
Orig. 60" Fir N.47°W., 14.5 ft., rotted off about 12"-18" above ground, no scribe found.
Set Brass cap at cor. mkd: County Surveyors Office
T 21 S R 5 W
¼ S4|S3
1965
New BTs- 21" D.Fir S.24°E., 13.8 ft. mkd. ¼ S3 CS BT.
41" D.Fir N.68°W., 37.0 ft. mkd. ¼ S4 CS BT.

BLM Resurvey by Bryan S. Seibold, Cadastral Surveyor, under Group #1564, Surveyed Aug/Nov. 1990 - (DCSO records Vol. 50 Page(s) 19061)

The ¼ sec. cor., perpetuated by Tracy in 1965, monumented with an iron post 1¼" dia., firmly set projecting 12" above ground with brass cap mkd. in 1965
from which the remains of the original bearing trees:
A sawed Fir stump 24" dia., bears S.75°E., 33 lks. dist., with a down Fir alongside 20" dia., with healed blaze.
A rotted Fir stump size indeterminate, bears N.47°W., 22 lks. dist., no marks visible.
and the remains of bearing trees mkd by Tracy:
A Fir 22" dia., bears S.23¼°E., 21½ lks. dist., with healed blaze.
A sawed Fir stump 41" dia., bears N.66°W., 56½ lks. dist., with healed blaze.
and a new bearing tree:
A Fir 5" dia., bears N.76¼°W., 14½ lks. dist. mkd. ¼ S4 BT