

Alias _____ Description _____
 Alias _____ Description _____
 Alias _____ Description _____
 Alias _____ Description _____

GLO Survey by Harvey Gordon, Deputy Surveyor, Under Contract #49, dated Oct. 17, 1854 - (DCSO records Vol. 2 Page(s) 784)

 Set post cor. of secs. 3, 4, 33 and 34, from which
 A R.Fir 24" dia., bears N.52°W., 65 lks. dist.
 A R.Fir 20" dia., bears N.45°E., 23 lks. dist.
 A R.Fir 36" dia., bears S.75°E., 39 lks. dist.
 A R.Fir 8" dia., bears S.21°W., 128 lks. dist.

Found and used corner in GLO survey by W. P. Wright, U.S. Deputy Surveyor, under Contract #514, dated August 27, 1884 (DCSO records Vol. 2 Page(s) 820)

BLM Resurvey by Floyd A. Brooks and Timothy A. Kent, Cadastral Surveyors, under Group #648, Surveyed Aug. 1967/Sept. 1971 - (DCSO records Vol. 37 Page(s) 15260-61)

 The Sec. Cor., determined at record bearing and distance from the remains of the original bearing trees:
 A decayed Fir stump 29" dia., bears S.75°E., 39 lks. dist., no marks visible.
 A root hole bears S.21°W., 128 lks. dist.
 A root hole bears N.52°W., 5 lks. dist.
 and trees of which I have no record:
 A decayed Fir stump 12" dia., bears N.56½°E., 9 lks. dist., with frag. scribe marks visible on decayed blaze
 A decayed Fir stump 8" dia., bears N.24½°W., 11 lks. dist., no marks visible.
 A sawed Fir stump 25" dia., bears N.73°W., 32½ lks. dist., with scribe marks D 6-24 J L 18 visible on opened blaze on butt portion of log lying nearby.

At the corner point
 Set an iron post, 28" long, 2 1/2" dia., 20" in the ground, with brass cap mkd:

T 20	S R 5 W
S 33	S 34
S 4	S 3
T 21	S
1967	

from which new bearing trees:
 A Fir 25" dia., bears S.86°E., 30 lks. dist. mkd. X at breast height and BT at base.
 A Fir 20" dia., S.14°E., 67 lks. mkd. T21S R5W S3 BT.
 A Fir 30" dia., bears S.33 3/4°W., 89 lks. dist. mkd. T21S R5W S4 BT.
 A Fir 25" dia., bears N.23°W., 165 lks. dist. mkd. T20S R5W S33 BT.
 No suitable tree available within limits in sec. 34.

PRIMARY CORNER DESCRIPTION Sec. Cor. for 3 & 4; 33 & 34, T20-5

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Douglas Co. Surveyors Office - Randall Smith and Stephen
Flause, crew - Nov. 12, 1991 - C.S. File 64/21-5

Found - 3¼" BLM brass cap on a 2½" O.D. iron pipe protrudes
3" above ground.

All evidence of original BTs are gone.
20" dia., 2 ft. high D.Fir stump, no marks visible,
bears N.77°W., 21.4 ft. (Rec. N.73°W., 21.4 ft. -
1967)

25" now 28" dia. D.Fir with a fully healed double
blaze, bears S.86°E., 19.8 ft. (agrees w/1967 BLM
rec.)

20" now 22" dia. tipped out of ground on face, D.Fir
root hole bears S.14°E., 44.2 ft. (agrees w/rec.
1967)

30" now 30" dia. 4½ ft. high D.Fir stump with a
fully healed single blaze, bears S.32°W., 58.7
ft. (Rec. S.33 3/4°W., 58.7 ft. - 1967 BLM)

25" now 24" dia. 4 ft. high D.Fir stump with a fully
healed single blaze and a galv. metal cap on top,
bears N.25°W., 108.9 ft. (Rec. N.23°W., 108.9 ft.
- 1967 BLM)

New BTs- 8" dia. Hemlock double blazed and scribed "T21S R5W
S34 CS BT" bears S.59½°E., 38.7 ft.

6" dia. D.Fir double blazed and scribed "T20S R5W
S34 CS BT", bears N.3°E., 55.7 ft.

No other reasonable trees. Corner lies approx. 30 ft. East
of a dirt skid road.

Note this is on the Douglas & Lane Co. line - check with Lane
Co for more corner information.