

TOWNSHIP 21 RANGE 05 POINT IDENTIFIER # 440400

PRIMARY CORNER DESCRIPTION 1/4 cor. for Secs. 15 and 22

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Harvey Gordon and Charles T. Gardner, Deputy Surveyors, under Contract #52 dated Feb. 17, 1855 (DCSO records Vol. 2 Page(s) 807)

Set ¼ sec. post, from which
A Fir 12" dia., bears S.43°E., 18 lks. dist.
A Fir 10" dia., bears N.4°W., 11 lks. dist.

Douglas County Surveyors Office - Vernon "Ray" Tracy and crew
Sept. 10, 1965 - C.S. File 54/14-14A

Looked for, not found.

BLM dependent resurvey by Wayne Rogers & Bryan Seibold Cadastral Surveyors & Robert Browning, Surveying Technician, under Group #1814, surveyed Aug. 1996/April 1998 - (DCSO rec. Vol. 53 Page(s) 20410-1)

From this point, the ¼ sec. cor. of secs. 15 & 22, determined at record bearing and dist. from the remains of the original bearing trees

A decayed fir stump, size indeterminate, bears S.43°E., 18 lks., with scribe marks ¼S BT visible on pitch stub sticking up from decayed stump.
A root hole, bears N.4°W., 11 lks., no remains of tree found.

At the corner point

Set a stainless steel post, 28" long, 2½" diam., 26" in the ground, with brass cap mkd.

T21S R5W
¼ $\frac{S\ 15}{S\ 22}$
1996

from which new bearing trees

A fir, 17" dia. bears S.63 ¾°E., 23½ lks. mkd. ¼ S22 BT.
A fir, 24" dia., bears N.0 ¾°W., 69 lks. mkd. ¼ S15 BT.