

TOWNSHIP 21 RANGE 05 POINT IDENTIFIER # 500140

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 34 and 35

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GL0 survey by Harvey Gordon and Charles T. Gardner, Deputy Surveyors, under Contract #52 dated Feb. 17, 1855 (DCSO records Vol. 2 Page(s) 800)

-----  
Set ¼ sec. post, drove charred stake, raised mound with trench as per instructions.

A.R. Evans, Deputy Co. Surveyor - March/April 1951 - M 19-53 and C.S. File 44/142

-----  
Set by proportion measure.  
Set 1" Iron pipe with brass cap mkd. ¼ S 34 & 35 T21S R5W Co. Surv. Off.  
Blaze and scribed BTs:  
54" Cedar S.59°W., 100.5 ft. mkd. ¼ S34 CS BT.  
18" Fir S.13°E., 128.5 ft. mkd. ¼ S 35 CS BT.

Douglas County Surveyors Office - Milo Godfrey and crew - Nov. 1964 - C.S. File 49/68-40

-----  
Looked for, not found.

Douglas Co. Surveyors Office - Randall Smith and Stephen Flause, crew - April 19, 1989 - C.S. File 62/63-11

-----  
Found - DCSO 2½" brass cap on a 1¼" O.D. Iron pipe, 2" below ground leaning 8" SE. of plumb.  
¾" bolt with nut protruding 8" above ground, bears N.44½°W., 0.8 ft. from DCSO BC/IP plumb position. (source unknown)  
18" Fir per Evans, is gone, probably removed by road work on highway.  
54" now 60" dia. 2½ ft. high Cedar stump with a previously opened blaze and axe mark, no scribing found bears S.49°W., 101.5 ft. (Rec. S.59°W. 100.5 ft.)  
¾" I.R. now bent ¾" bolt, bears S.1°W., 170.8 ft. (agrees well with record. M 19-53)  
⅝" I.R. bears S.1°W., 223.68 ft. (agrees well with record per M 81-72)  
DCSO BC/IP returned to plumb position, BC is flush with ground. Position of corner as determined by Evans, perpetuated by New BTs below:  
24" D.Fir double blazed and scribed "¼ S34 CS BT" bears S.49¼°W., 50.7 ft.

(Cont. Next Page)

TOWNSHIP 21 RANGE 05 POINT IDENTIFIER # 500140

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 34 and 35

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

A double trunked I.Cedar double blazed and scribed  
"¼ S35 CS BT" on 7" SW. trunk, bears S.38°E.,  
69.9 ft. to root crown.  
Corner is approx. 140 ft. North of highway.

Douglas Co. Surveyors Office - Randall Smith and Stephen  
Flause, crew - March 29, 1990 - C.S. File 64/6-11  
-----  
Found - A 2½" dia. DCSO brass cap on a 1¼" O.D. Iron pipe  
flush with ground.  
¾" bolt with nut, protruding 8' above ground,  
bears N.44½°W., 0.8 ft. from DCSO BC/IP.  
BTs and B0s found as recorded in 1989.  
All references with the exception of the 5/8" I.R. bearing  
S.1°W., 223.68 will be destroyed in near future by new  
highway construction.  
New BTs- 9" dia. I.Cedar double blazed and scribed "¼ S34 CS  
BT" bears S.82°W., 96.8 ft.  
19" dia. D.Fir double blazed and scribed "¼ S35 CS  
BT" bears N.39½°E., 197.4 ft.  
13" dia. double trunked I.Cedar double blazed and  
scribed "¼ S35 CS BT" on West trunk, root crown  
bears N.55½°E., 176.3 ft.

Fd. OK, Aug. 1992 by B. Rogers - Land partition 1992-0059  
Fd. 1/2021 by D. Edwards - M179-2