

TOWNSHIP 21 RANGE 05 POINT IDENTIFIER # 500200

PRIMARY CORNER DESCRIPTION Sec cor for 26, 27, 34 and 35

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GL0 survey by Harvey Gordon and Charles T. Gardner, Deputy Surveyors, under Contract #52 dated Feb. 17, 1855 (DCSO records Vol. 2 Page(s) 800)

Set post cor. of secs. 26, 27, 34 and 35, from which
A Fir 36' dia., bears N.23°E., 24 lks. dist.
A Fir 8" dia., bears S.30°E., 28 lks. dist.
A Fir 6" dia., bears N.17°W., 11 lks. dist.
A Redwood 8" dia., bears S.69°W., 56 lks. dist.

O.F. Thiel - For: J.O. Johnson - Jan. 26, 1901 - F.B. 113
Page 104

No trace of old bearing trees to be found. Set Maple post.

A.R. Evans, Deputy Co. Surveyor - March/April 1951 - M 19-53
and C.S. File 44/142

Found - Cedar stake mkd. S26 27 34 and 35. Stake checks for bearing and distance.
One O.B.T. down, 36" Fir N.23°E., 24 lks.
Set 3/4" Iron rod.
New BTs- 24" Maple N.33¼°W., 32.5 ft. mkd. S27 T21S R5W.
16" Maple S.71½°E., 12.0 ft. S35 T21S R5W CS BT.

Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy -
Stoffel and Stone, crew - Dec. 1964 - C.S. File 49/68-50

Found - Old scribed stake, rotted off at ground & 3/4" I.R. Badly rotted, old uprooted Fir, N.23°E., 15.8 ft., on under side found bark with flattened area showing fragmentary bark scribing.
Cedar stump S.69°W., 37.0 ft. showing evidence of upper and lower faces, but no scribing, faces badly rotted.
No trace of orig. SE. or NW. bearing trees.
15" Maple S.73°E., 11.0 ft. scribing visible "21R 5 S35 CS BT"
27" Maple N.34°W., 32.0 ft. scribing visible "T21S R5W S27 CS"
DID NOT SET BRASS CAP.
New BTs- 6" D.Fir N.81°E., 4.5 ft. mkd. T21S R5W S26 CS BT.
13" I.Cedar S.51°W., 23.3 ft. T21S R5W S34 CS BT.

Fd. OK, Dec. 8, 1970, DCSO - C.S. File 54/14-47(2ND PG)
Fd. OK, Feb. 1981 by R. Kimberling - M 79-69

TOWNSHIP 21 RANGE 05 POINT IDENTIFIER # 500200

PRIMARY CORNER DESCRIPTION Sec cor for 26, 27, 34 and 35

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

BLM dependent resurvey by Wayne Rogers & Bryan Seibold Cadastral Surveyors & Robert Browning, Surveying Technician, under Group #1814, surveyed Aug. 1996/April 1998 - (DCSO rec. Vol. 53 Page(s) 20396-7)

The cor. of secs. 26, 27, 34 and 35, perpetuated by O.F. Thiel, in 1901, further perpetuated by Evans, in 1951, further perpetuated by Godfrey, in 1964, monumented with an iron rod, 3/4 in. diam., firmly set, projecting 10" above ground, from which the remains of the original bearing trees

A root hole, bears N.23°E., 24 lks., with uprooted decayed fir trunk, size indeterminate, alongside, no marks visible.

A decayed cedar stump, 18" dia., bears S.69°W., 56 lks., no marks visible. (Record, redwood)

and bearing trees mkd. by Evans

A maple, 16" diam., bears S.71½°E., 16 lks., with healed double blazes.

A maple, 29" dia., bears N.33¾°W., 49 lks., with no marks visible.

and bearing trees mkd. by Godfrey

A fir, 15" diam., bears N.81°E., 7 lks., with healed double blazes.

A cedar, 23" diam., bears S.51°W., 35½ lks., with healed double blazes.

At the corner point

Set a stainless steel post, 28" long, 2½" diam., 26" in the ground, directly over the iron rod, with brass cap mkd.

T 21 S R 5 W
S 27 | S 26
S 34 | S 35
1997

from which a new bearing tree

A cedar, 8" dia., bears N. 79½°W., 12 lks., mkd. T21S R5W S27 BT.

Deposit a magnet in a white plastic case at the base of the stainless steel post.

Fd. OK by L. Roberts, Jan. 2001 - M136-43

Found OK by C. Sweeden, April 2003 - M142-9