

TOWNSHIP 21 RANGE 05 POINT IDENTIFIER # 500340

PRIMARY CORNER DESCRIPTION 1/4 cor. for Secs. 22 and 23

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Harvey Gordon and Charles T. Gardner, Deputy Surveyors, under Contract #52 dated Feb. 17, 1855 (DCSO records Vol. 2 Page(s) 802)

Set 1/4 sec. post, from which
A Fir 8" dia., bears N.8°W., 90 lks. dist.
A Fir 6" dia., bears N.2°E., 88 lks. dist.

Douglas County Surveyors Office - Vernon "Ray" Tracy and crew
Sept. 14, 1965 - C.S. File 54/14-4

Found - Orig. 8" Fir N.8°W., 19.4 ft., now 36" rotted stump,
found scribing "1/4 S BT"
No trace of NE. BT.
Set 3/4" Iron rod, 18" in ground, 6" out of ground at corner.
New BTs- 12" D. Fir N.66°W., 29.7 ft. mkd. 1/4 S22 CS BT.
6" D. Fir S.77°E., 27.8 ft. mkd. 1/4 S23 CS BT.
Corner lies on a steep North slope approx. 200 ft. North of
spur ridge and 100 ft. South of small creek.

BLM Resurvey by Bryan S. Seibold, Cadastral Surveyor, under
Group #1639, surveyed Sept. 1992/April 1993. - (DCSO records
Vol. 51 Page(s) 19399)

The 1/4 sec. cor., perpetuated by Tracy in 1965, monumented
with an iron rod, 3/4" dia., firmly set, projecting 10" above
ground, from which the remains of an original bearing tree:
A rotted Fir stump 36" dia., bears N.8°W., 90 lks. dist.,
with scribe marks 1/4 S BT visible on open blaze.
and bearing trees mkd. by Tracy:
A Fir 14" dia., bears S.78 1/2°E., 42 lks. dist., with healed
blaze.
A Fir 24" dia., bears N.65 1/4°W., 44 lks. dist., with healed
blaze.

At the corner point
Set an stainless steel post, 28" long, 2 1/2" dia., 24" in
the ground, directly over the iron rod, with brass cap mkd:
T 21 S R 5 W
1/4
S 22 | S 23
1993

No new accessories taken.

Survey by Les Roberts - For: Giustina Resources Inc. &
Giustina Timber Co. - July 30, 1993 - M 117-53

Found - 1993 BLM Iron pipe and brass cap.
(Cont. Next Page)

