

TOWNSHIP 21 RANGE 05 POINT IDENTIFIER # 500640

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 2 and 3

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by W. P. Wright, U.S. Deputy Surveyor, under Contract #514, dated August 27, 1884 (DCSO records Vol. 2 Page(s) 817-18)

Set post 4" dia., 4 ft. long, with mkd. stone 12" in ground for ¼ sec. cor. mkd. ¼ S on W. face, from which
A Fir 60" dia., bears N.88°E., 38 lks. dist. mkd. ¼ SBT
A Fir 10" dia., bears N.57°W., 21 lks. dist. mkd. ¼ SBT

Douglas County Surveyors Office - Vernon "Ray" Tracy and crew Aug/Sept. 1965 - C.S. File 54/14-10

Found - Orig. 10" now 21" Fir, N.57°W., 13.9 ft., turned out, find "¼S" scribe in previously opened scar. Orig. 60" Fir N.88°E., 25.1 ft., badly burned & rotted stump, no scribe.

Set Brass cap at cor. mkd: County Surveyors Office
T 21 S R 5 W
¼ S3|S2
1965

New BTs- 17" D.Fir, N.33°W., 19.2 ft. mkd. ¼ S3 CS BT.
9" Hemlock N.5°E., 21.7 ft. mkd. ¼ S2 CS BT.
Corner lies approx. 80 ft. North of small creek, flowing SE.

BLM Resurvey by Bryan S. Seibold, Cadastral Surveyor, under Group #1564, Surveyed Aug/Nov. 1990 - (DCSO records Vol. 50 Page(s) 19050-51)

The ¼ sec. cor., perpetuated by Tracy in 1965, monumented with an iron post, 1½" dia., firmly set, projecting 10" above ground, with brass cap mkd. in 1965

from which the remains of the original bearing trees:
A root hole, bears N.88°E., 38 lks. dist.
A root hole, bears N.57°W., 21 lks. dist., with uprooted Fir alongside, 21" dia., with fragmentary scribe marks visible on opened blaze.

and the remains of the bearing trees mkd. by Tracy:
A Hemlock 13" dia., bears N.5°E., 33 lks. dist., with healed double blaze.
A sawed Fir stump 20" dia., bears N.31½°W., 29½ lks. dist., with healed blaze.

and a new bearing tree:
A Maple 23" dia., bears S.36°W., 16½ lks. dist. mkd. ¼ S3 BT.