

PRIMARY CORNER DESCRIPTION Sec. Cor. for 35 & 36; 1 & 2, T22-5

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by Gordon and Gardner, under Contract #52 dated Feb. 17, 1855 (DCSO records Vol. 2 Page(s) 790-791)

-
- Set post cor. of secs. 1, 2, 35 and 36, from which
- A Fir 30" dia., bears N.55°W., 16 lks. dist.
 - A Fir 30" dia., bears N.12°E., 139 lks. dist.
 - A Fir 50" dia., bears S.70°E., 45 lks. dist.
 - A Fir 15" dia., bears S.28°W., 84 lks. dist.

B.H. McGillicuddy - Wit: Marvin; Yoder; Martin; Olson - July 1953 - C.S. File 41/182

This corner described on 1952 map (RM 1-40) as: Post at junction of two fences.

Orig. BTs:

- Fir 30" N.55°W., 16 lks. (defaced stump)
- Fir 30" N.12°E., 134 lks. (burned windfall)
- Fir 50" S.70°E., 45 lks. (burned stump)
- Fir 15" S.28°W., 82 lks. (destroyed)

Found iron capped pipe, 1953.

New BTs -14" Fir N.65°E., 30.8 ft. mkd. Tp21S R5W Sec. 36 BT

8" Fir S.55°E., 16.5 ft. mkd. Tp 22S R5W Sec. 1 BT.

Old BT - 36" Fir stump N.55°W., 10.0 ft. mkd. S35 BT.

Cor. and BTs found OK, Aug. 1972, B.Shaner, M 42-68

BLM resurvey by James E. Jelley and Wayne L. Rogers, under Group #1103, surveyed June/July 1982 (DCSO records Vol. 46 Page(s) 17595-96)

The Sec. cor., perpetuated and recorded by McGillicuddy in 1953, monumented with an iron rod, 1" dia., firmly set, projecting 3" above ground, from which the remains of the original bearing trees:

A root hole bears N.12°E., 139 lks. dist., with a down Fir alongside, size indeterminate; no marks visible.

A sawed Fir stump 30" dia., bears N.55°W., 16 lks. dist., with scribe marks S35 BT visible on an opened blaze.

and bearing trees mkd. by McGillicuddy:

A Fir 26" dia., bears N.65°E., 49 lks. dist., with healed blaze.

A Fir 18" dia., bears S.55°E., 25 lks. dist., with healed blaze.

At the corner point

Set an iron post, 28" long, 2½" dia., 24" in the ground, with brass cap mkd:

(Cont. Next Page)

TOWNSHIP 21 RANGE 05 POINT IDENTIFIER # 600100

PRIMARY CORNER DESCRIPTION Sec. Cor. for 35 & 36; 1 & 2, T22-5

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

T 21 S	R 5 W
S 35	S 36
S 2	S 1
T 22 S	R 5 W

1982

from which the new bearing trees

A Grand Fir 6" dia., bears S.47°W., 44 lks. dist., mkd.
T22S R5W S2 BT.

A Fir 16" dia., bears N.27°W., 21½ lks. dist., mkd. T21S
R5W S35 BT.

FD. OK, Dec. 1997 - by Les Roberts - M 128-1
Found OK by T. Rambo, Jan. 2004 - M143-75

DCSO-GIS Corner visitation - 10/13/2005 - Typed: 1/19/2011 -
C.S. File 67/33-1

Monument - 3" Al. cap on al. pipe.
Comment - 1 live bt, 2 stumps.

Fd. Ok by Kris DeGroot, 7/2007 - M153-59

Douglas Co. Surveyors Office - Stephen J. Flause - Mike
Koch - Garrett McGraw - April 27, 2011 - C.S. File 67/33-39

Found - Capped iron pipe noted as found in 1953 and
described as a 1" dia., iron rod in 1982 is not
seen (possibly buried when 1982 monument was set)
(1982) A 3¼" dia., alum. cap (properly mkd) on a 2½"
I.D. alum. pipe is plumb and firmly set
protruding 3" above ground.

(Orig) A fir 30" dia., now a very rotted 36" dia.,
3 ft. tall fir stump with no remaining marks or
blazes; bears N.58°W., 11.4 ft. (rec. N.55°W.,
10.6 ft. - a good face distance)

We do not look for orig. NE BT; numerous reprod
trees block measurement.

(Orig) A fir 50" dia., now a possible but indistinct
root-hole; bears S.70°E., 29.7 ft. (as per rec)

(Orig) A fir 15" dia., now a 20" dia., 3½ ft. tall
fir stump (now grown into edge of larger, younger
stump to SE) with the partial remains of a blaze
showing the clear scribing "S2"; bears S.28°W.,
55.4 ft. (as per rec)

(1953) A 14" fir now a 28" DBH D.Fir stump with a
fully healed single blaze, bears N.65°E., 32.3
ft. (record N.65°E. 30.8 ft agrees with 1982 rec)

continued next page

TOWNSHIP 21 RANGE 05 POINT IDENTIFIER # 600100

PRIMARY CORNER DESCRIPTION Sec. Cor. for 35 & 36; 1 & 2, T22-5

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

An 8" fir now a 27" DBH D.Fir with a fully healed single blaze; bears S.58°E., 16.5 ft. (rec. S.55°E., 16.5 ft)
(1982) A G.Fir 6" dia., now a down & bark-less fir 12" in dia., with an unhealed single blaze with the scribing "T22S R5W S22" (lower blaze rotted). Tree is out of position but shallow root depression bears S.47°W., 29.0 ft. (as per rec)
A fir 16" dia., is not found.
A galvanized steel post protruding 3 ft. above ground is set 1 ft. SW from monument.
New BTs- A 27" DBH D.Fir scribed "T22S R5W S1 CS" "BT" on a double blaze; bears S.10½°E., 33.0 ft.
A 9" DBH D.Fir scribed "T21S R5W S35 CS" "BT" on a double blaze; bears N.56½°W., 35.6 ft.
Note - Monument is in newer reprod. Forest on moderate northeasterly slope with an old-growth forest in the SE quadrant.
Compass decl. 15¾°E.