

TOWNSHIP 21 RANGE 05 POINT IDENTIFIER # 600140

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 35 and 36

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

<p>GL0 survey by Harvey Gordon and Charles T. Gardner, Deputy Surveyors, under Contract #52 dated Feb. 17, 1855 (DCS0 records Vol. 2 Page(s) 794)</p> <p>-----</p> <p>Set ¼ sec. post, from which A Fir 6" dia., bears N.17°W., 46 lks. dist. A Fir 6" dia., bears S.78°E., 73 lks. dist.</p>
<p>B.H. McGillicuddy - July 1953 - C.S. File 41/182</p> <p>-----</p> <p>Set post and iron pipe. Original BTs: 6" Fir S.78°E., 48.18 ft. (Fir stump) scribe visible. 6" Fir N.17°W., destroyed. New BTs: 30" Fir N.24°E., 46.8 ft. 32" Fir S.54½°W., 26.7 ft.</p>
<p>Douglas Co. Surveyors office - Dec. 1964 - C.S. File 49/68-57</p> <p>-----</p> <p>Cor. Fd. OK. Found 3/4" Iron pipe, wooden stake and both trees mkd. in 1953, in good condition. Good scribing still visible on stump of orig. SE. BT "¼S".</p>
<p>Fd. OK, Feb. 1981 by R. Kimberling - M 79-69</p>
<p>Les Roberts for: Giustina Resources Inc. Jan. 1996 - M123-29.</p> <p>-----</p> <p>Found - 3/4" iron pipe set by B.M. McGillicuddy in C.S. 41/182</p> <ul style="list-style-type: none">- 12" Fir stump, S.78°E., 49.7 ft. (scribe vis.) 1855 BT- 48" Fir snag, S.54°W., 26.7 ft. (scar vis.) 1953 BT- 31" Fir Stump, N.24°E., 46.6 ft. (scribe vis.) 1953 BT <p>New BTs -</p> <ul style="list-style-type: none">- 10" Fir, N.20°W., 18.5 ft. (scribed/painted red) 1994 Riley BT)- 12" Fir, S.07°W., 12.7 ft. (scribed/painted red) 1994 Riley BT) <p>Found 5/8" iron pin set by Gerald Riley in Nov. 1994. Pin bears N.63°46'W., 7.64 ft. Also BT's by Riley in Nov. 1994:</p> <ul style="list-style-type: none">- 10" Fir, S.51°E., 16.4 ft. (scribe vis.), 1994 BT- 10" Fir, North, 13.9 ft. (scribe vis.), 1994 BT- 12" Fir, S.19°E., 16.9 ft. (scribe vis.), 1994 BT- 12" Fir, N.31°E., 23.5 ft. (scribe vis.), 1994 BT
<p>Fd. OK - Les Roberts - Dec. 1997 - M 128-1</p>

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 35 and 36

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

BLM dependent resurvey by Wayne Rogers & Bryan Seibold Cadastral Surveyors & Robert Browning, Surveying Technician, under Group #1814, surveyed Aug. 1996/April 1998 - (DCSO rec. Vol. 53 Page(s) 20394-6)

The ¼ cor. of secs. 35 & 36, perpetuated by McGillicuddy, in 1953, further perpetuated by Roberts, in 1996, monumented with an iron pipe, 1¼" diam., firmly set, projecting 5", above ground, from which the remains of an original bearing tree

A sawed fir stump, 10" diam., bears S.78°E., 73 lks., with scribe marks BT visible on opened blaze.

and the remains of bearing trees mkd. by McGillicuddy

A sawed fir stump, 36" diam., bears N.24°E., 73 lks., with scribe marks BT visible on decayed face.

A fir snag, 50" diam., bears S.54½°W., 44 lks., no scribe marks visible on opened blaze.
and bearing trees recorded by Roberts

A fir, 17" diam., bears S.7°W., 19 lks., with fragmentary scribe marks visible on partially healed blaze.
(Roberts reported this tree was mkd. by Riley in 1994)

A fir, 11" diam., bears N.20°W., 28 lks., with fragmentary scribe marks visible on partially healed blaze.
(Roberts reported this tree was mkd. by Riley in 1994)

At the corner point

Set a stainless steel post, 28", long, 2½" diam., 26" in the ground, directly over the iron pipe, with brass cap mkd.

T 21 S R 5 W

¼
S 35 | S 36
1997

from which new bearing trees

A fir, 6" diam., bears N.89°E., 31½ lks., mkd. ¼ S36 BT.

A fir, 4" diam., bears N.35°W., 16 lks., mkd. ¼ S35 BT.

Deposit a magnet in a white plastic case at the base of the stainless steel post.

From this point, the point erroneously remonumented as the ¼ sec. cor. of secs. 35 & 36, by Gerald D. Riley, in 1994, preliminary file located at the Douglas County Surveyors Office, map file P-94(C.S. 65/41-8), bears N.63°28'42"W., 0.115 chs., monumented with an iron rod, 5/8" dia., firmly set, projecting 8", above ground, with red plastic cap mkd. RILEY PLS 705, from which bearing trees mkd. by Riley

A fir, 17" dia., bears N.31°E., 35½ lks., with fragmentary scribe marks visible on partially healed blaze.

A fir, 13" diam., bears S.51°E., 25 lks., with fragmentary scribe marks visible on partially healed blaze.

continued next page

TOWNSHIP 21 RANGE 05 POINT IDENTIFIER # 600140

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 35 and 36

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

A fir, 17" dia., bears S.19°E., 25½ lks., with fragmentary scribe marks visible on partially healed blaze.
A fir, 11" diam., bears North, 21 lks., with fragmentary scribe marks visible on partially healed blaze.

Found OK by Les Roberts, April 2000 - M134-66