

TOWNSHIP 21 RANGE 05 POINT IDENTIFIER # 600200

PRIMARY CORNER DESCRIPTION Sec Cor for 25, 26, 35 and 36

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GL0 survey by Harvey Gordon and Charles T. Gardner, Deputy Surveyors, under Contract #52 dated Feb. 17, 1855 (DCSO records Vol. 2 Page(s) 794)

Set post cor. for secs. 25, 26, 35 and 36, from which
A W.Oak 20" dia., bears S.10°E., 138 lks. dist.
A W.Oak 18" dia., bears S.28°W., 260 lks. dist.
A W.Oak 10" dia., bears N.69°W., 844 lks. dist.
A W.Oak 20" dia., bears N.42°E., 231 lks. dist.

Douglas County Surveyors Office - Milo Godfrey and crew -
C.S. File 49/68-55 - Dec. 1964

Corner searched for, not found.

BLM dependent resurvey by Wayne Rogers & Bryan Seibold Cadastral Surveyors & Robert Browning, Surveying Technician, under Group #1814, surveyed Aug. 1996/April 1998 - (DCSO rec. Vol. 53 Page(s) 20393-4)

At the of secs. 25, 26, 35 36, at proportionate dist. there is no remaining evidence of the original cor.
Set a stainless steel post, 28", long, 2½" diam., 28" in the ground, with brass cap mkd. T 21 S R 5 W

S 26 | S 25
S 35 | S 36
1997

from which

A fir, 13" diam., bears S.11½°E., 402 lks., mkd. T21S R5W S36 BT.

An oak, 10" diam., bears S.16¼°W., 242 lks., mkd. T21S R5W S35 BT.

A fir, 57" diam., bears N.85 3/4° W., 111 lks., mkd. T21S R5W S26 ST.

No suitable accessory available in the NE quadrant.

Deposit a magnet in a white plastic case at the base of the stainless steel post.

The cor. is located in a grassy field and E., 1.90 chs. from a graveled driveway, 30 lks. wide, bears N.15°W. and S.35°E.

Found 1997 BLM BC by D. Bentz, Jan. 1998 - 1998-0023A&B

Found OK by L. Roberts, May 2000 - M134-75