

TOWNSHIP 21 RANGE 05 POINT IDENTIFIER # 600340

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 23 and 24

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Harvey Gordon and Charles T. Gardner, Deputy Surveyors, under Contract #52 dated Feb. 17, 1855 (DCSO records Vol. 2 Page(s) 796)

Set ¼ sec. post, from which
A Fir 24" dia., bears N.64°W., 68 lks. dist.
A Fir 12" dia., bears N.65°E., 30 lks. dist.

Douglas County Surveyors Office - Vernon "Ray" Tracy and crew
Sept. 2, 1965 - C.S. File 54/14

Looked for, not found.

Survey by Jim S. Peterson - For: Doug Smith - June 1977 - M
65-47

Found - Rotted Fir stump bears N.64°W., 44.88 ft.
Set 3/4" Iron pipe.
New BTs- 12" D.Fir bears N.68°E., 9.3 ft. to center, scribed
¼ S24 BT.
12" D.Fir bears S.81°W., 12.4 ft. to center, scribed
¼ S25 BT.
Corner falls 2.1 ft. N.24°W. of fence corner.