

PRIMARY CORNER DESCRIPTION Sec. Cor. for 11, 12, 13 and 14

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Harvey Gordon and Charles T. Gardner, Deputy Surveyors, under Contract #52 dated Feb. 17, 1855 (DCSO records Vol. 2 Page(s) 797)

Set post cor. of secs. 11, 12, 13 and 14, from which

- A Fir 18" dia., bears N.62°E., 50 lks. dist.
- A Fir 6" dia., bears N.67°W., 69 lks. dist.
- A Fir 36" dia., bears S.18°E., 83 lks. dist.
- A Fir 30" dia., bears S.10°W., 138 lks. dist.

Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy - Vernon Tracy; Clete Putnam, crew - Jan. 1962 - C.S. File 49/89-45

Found - Rotted Fir stump, N.67°W., 45.5 ft., scribing visible on old face.

- Badly burned Fir snag, N.62°E., 33.0 ft., no scribing found.
- Fir tree, now 60", S.18°E., 54.8 ft. Old injury on bark, no scribing found.
- Fir stump, North face burned away, S.10°W., 91.1 ft., no scribing found.

Set Brass cap at cor. mkd: County Surveyors Office

T	21	S	R	5	W
	<u>S 11</u>		<u>S 12</u>		
	S 14		S 13		
			1962		

Blaze and rescribe: 60" Fir S.18°E., 57.0 ft., to center, "T21S R5W S13 CS BT".

- New BTs- 18" D.Fir N.48°E., 37.3 ft. mkd. T21S R5W S12 CSBT
- 6" D.Fir N.45°W., 27.0 ft. mkd. T21S R5W S11 CS BT
- 18" D.Fir S.5°W., 58.2 ft. mkd. T21S R5W S14 CS BT

Fence corner, fences E. and N., bears East, 24 ft.

Fd. OK, June 1990 - M 110-25

BLM dependent resurvey by Wayne Rogers & Bryan Seibold Cadastral Surveyors & Robert Browning, Surveying Technician, under Group #1814, surveyed Aug. 1996/April 1998 - (DCSO rec. Vol. 53 Page(s) 20407-8)

The cor. of secs. 11, 12, 13 & 14, perpetuated by Godfrey, in 1962, monumented with an iron post, 1½" diam., firmly set, projecting 12", above ground, with properly mkd brass cap, from which the remains of the original bearing trees

- A fir, 62" diam., bears S.17°E., 85 lks., with no marks visible. (Record, S.18°E., 83 lks.)

continued next page

TOWNSHIP 21 RANGE 05 POINT IDENTIFIER # 600500

PRIMARY CORNER DESCRIPTION Sec. Cor. for 11, 12, 13 and 14

Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____

A decayed fir stump, 30" diam., bears S.10°W., 138 lks., with no marks visible.
A decayed fir stump, size indeterminate, bears N.68 3/4°W., 69 lks., with old axe marks visible. (Record, N.67°W.)
and bearing trees mkd. by Godfrey
A sawed fir stump, 31" diam., bears N.48°E., 56½ lks., with healed double blazes.
A fir, 29" diam., bears S.5°W., 88 lks., with healed double blazes.
A fir, 19" diam., bears N.45°W., 41 lks. with healed double blazes.
and a new bearing tree
A fir, 15" dia. bears N.8°E., 35 lks. mkd: T21s R5W S12 BT