

TOWNSHIP 21 RANGE 05 POINT IDENTIFIER # 600540

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 11 and 12

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Harvey Gordon and Charles T. Gardner, Deputy Surveyors, under Contract #52 dated Feb. 17, 1855 (DCSO records Vol. 2 Page(s) 798)

Set ¼ sec. post, from which
 A Cedar 12" dia., bears S.80°W., 73 lks. dist.
 A Fir 20" dia., bears N.39°E., 152 lks. dist.

O.F. Thiel - For: Pioneer Lumber co. - April 1928 - F.B. 116
Page 31

Cor. stands W. of blazed line. Set a Fir post and remarked
NE. tree. SW. tree dead.

Douglas County Surveyors Office - Vernon "Ray" Tracy and crew
Sept. 2, 1965 - C.S. File 54/14-15A

Looked for, not found.

Survey by Les Roberts - For: Seneca Timber Co. - June 1990 -
M 110-25

No Corner Monument Found. Corner re-established from 2 1854
BTs.
Found - 26" Cedar stump, S.76°W., 48.2 ft. No marks.
 48" Fir snag, N.42°E., 100.3 ft. No marks.
Using face measurement from found BTs, SET 5/8" Iron pin with
yellow plastic cap mkd. "Roberts P.L.S. 1039".
New BTs- 9" Fir S.09°W., 14.8 ft., scribed/painted red.
 14" Fir N.82°E., 17.4 ft., scribed/painted red.