

TOWNSHIP 21 RANGE 06 POINT IDENTIFIER # 100100

PRIMARY CORNER DESCRIPTION SW Cor. Sec. 31 (Tsp corner)

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GL0 survey by Gordon and Gardner, under Contract #52 dated Feb. 17, 1855 (DCSO records Vol. 2 Page(s) 694) (& Pg. 631)

Set post cor. of Townships 21 and 22 S., Ranges 6 & 7 West; from which

- A Fir 18" dia., bears N.59°E., 57 lks. dist.
- A Fir 24" dia., bears S.28°E., 13 lks. dist.
- A Cedar 10" dia., bears S.68°W., 9 lks. dist.
- A Fir 20" dia., bears N.32°W., 104 lks. dist.

GL0 survey by Laban H. Wheeler, Under Contract #467 dated April 7, 1883 (DCSO records Vol. 2 Page(s) 549)

At the cor. to Town. 21 & 22 S., Rgs. 6 & 7 W. I found the post much decayed and one of the witness trees blown down. I reestablished the same by setting a post 6" dia., 4 ft. long, 24" in ground, mkd. T21S S31 on NE.; R6W S6 on SE.; T22S S1 on SW.; R7W S36 on NW. face, with 6 notches on each edge, from which

- Fir 20" dia., bears N.57°E., 56 lks. dist. mkd. T21S R6W S31 BT.
- Cedar 14" dia., bears S.71°W., 10 lks. dist. mkd. T22S R7W S1 BT.
- Fir 40" dia., bears S.23°E., 60 lks. dist. mkd. T22S R6W S6 BT.
- Fir 20" dia., bears N.17°W., 80 lks. dist. mkd. T21S R7W S36 BT.

Wilford N. Haines - Feb. 17, 1960 - C.S. File 51/67-2

Set 1" x 1" x 36" T Iron from old BTs.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy, Joe Brady, Jack Heritage, crew - Sept. 1, 1966 - C.S. File 54/14-20

Found - Haines T Iron under a 16" log, set from orig. BTs. Orig. 20" now 28" Fir snag, N.59°E., 37.6 ft. Open and find "31 T21 6W" scribe.

All other BTs destroyed.

Set Brass cap at cor. mkd: County Surveyors Office
T21S R7W S 36 | S 31
T22S S 1 | S 6 R6W
1966

- New BTs -7" Hemlock N.26°W., 13.2 ft. mkd. T21S R7W S36 CSBT
- 9" Hemlock N.80°E., 24.9 ft. mkd. T21S R6W S31 CSBT
- 26" R.Cedar S.61°E., 29.9 ft. mkd. T22S R6W S6 CSBT

No suitable tree close to SW. Cor. lies on steep NW. slope.
(Cont. Next Page)

TOWNSHIP 21 RANGE 06 POINT IDENTIFIER # 100100

PRIMARY CORNER DESCRIPTION SW Cor. Sec. 31 (Tsp. cor.)

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

BLM resurvey, by Boyd W. Peterson, under special instructions dated August 18, 1986, Group #1346, Surveyed Sept/Dec. 1986 (DCSO records Vol. 48 Page(s) 18306

The Tsp. corner, perpetuated and recorded by Haines in 1960, and further perpetuated and recorded by Tracy in 1966, monumented with a "T" shaped iron rod, 1" dia., firmly set, projecting 3" above ground, from which the remains of the original bearing trees

A Fir snag 28" dia., bears N.59°E., 57 lks. dist., with fragmentary scribe marks visible on opened blaze.

A Cedar 38" dia., bears S.68°W., 14 lks. dist., with burned out face. (Rec. 9 lks.)

and bearing trees mkd. by Tracy

A Hemlock 14" dia., bears N.80°E., 36 lks. dist., with healed blaze.

A Cedar 27" dia., bears S.59½°E., 45 lks. dist. with healed blaze.

A Hemlock 14" dia., bears N.27°W., 19 lks. dist., with healed blaze.

Set an stainless steel post, 28" long, 2 1/2" dia., 24" in the ground, directly over "T" shaped iron rod, with brass cap mkd:

T 21 S	
R 7 W	R 6 W
<u>S 36</u>	<u>S 31</u>
S 1	S 6
T 22 S	
1986	

Deposit a white "DEEP-1" magnetic marker at base of stainless steel post.

From this point, a reference point established and recorded by Tracy, in 1966, bears South 0.008 chs. dist., monumented with an iron pipe 1½" dia., firmly set, projecting 15" above ground with plastic cap mkd. DOUG. CO. SURVEYOR.

Fd. and used in BLM resurvey by Rogers and Bedell, Group #1392, surveyed Aug/Nov. 1987 (DCSO records, Vol. 48 Page 18462)

Les Roberts, L.S. 1039 - For: Seneca Jones Timber Co. - Dec. 1994 - M 121-27

CONDITION REPORT ONLY

Found - 1986 BLM iron pipe & brass cap.

28" Fir snag, N.59°E., 37.0' (scribe vis), 1855 BT.

(Cont. Next Page)

TOWNSHIP 21 RANGE 06 POINT IDENTIFIER # 100100

PRIMARY CORNER DESCRIPTION SW Cor. Sec. 31 (Tsp. Cor)

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

1966 Douglas County brass cap, 0.55' south of 1986
BLM iron pipe & brass cap.
14" Hemlock, N.26°W., 13.2' (scribe vis.), 1966 BT.
15" Hemlock, N.80°E., 25.0' (scribe vis.), 1966 BT.
30" Hemlock, S.61°E., 30.0' (scribe vis.), 1966 BT.

David Edwards - For: Seneca Jones Timber Co. - Nov 2012 -
C.S. File 65/75-11

Found - Brass cap
34" hemlock S.61°E., 30.0' with healed blaze
36" hemlock (BLM tag only no blaze) S.80°W., 9.0'
16" hemlock N.26°W., 13.2' with healed blaze
Steel fence post 2' north

BLM dependent resurvey by Jeffrey O. Covington, Cadastral
Surveyor, under Group No. 2824, surveyed May 2016/March 2018
- (DCSO records Vol. 59 Page(s) 23871-2)

The cor. of Tps. 21 and 22 S Rgs. 6 and 7 W., monumented with
a stainless steel post, 2½" dia., firmly set, projecting 4"
above ground, with brass cap (properly) mkd.
from which the remains of the original bearing trees reported
by Peterson in 1986
A decayed fir stump, size indeterminate, bears N.59°E.,
37.6 ft., with axe marks visible on bark.
A cedar, 43" dia., bears S.68°W., 9.2 ft. with a hollowed
blaze.
and the remains of the bearing trees mkd. by the Douglas
County Surveyor's Office in 1966
A root hole bears N.80°E., 23.8 ft., alongside of which is
a hemlock snag, 16" dia., with a healed blaze.
A cedar, 35" dia., bears S.59½°E., 29.7 ft., with a healed
blaze.
A hemlock, 19" dia., bears N.27°W., 12.5 ft., with a
healed blaze.
and a new bearing tree
A hemlock, 17" dia., bears N.45½°E., 19.5 ft., mkd. T21S
R6W 331 BT.
Each new BT has a 2½"x ¼" magnetic nail (Mag Nail) driven at
the base right side-center & each monument established or
remonumented has a magnet deposited in a white plastic case
at the base of the stainless steel post. Alum. Angle iron
driven alongside each monument.