

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 31 & 32

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Wm. P. Wright, Deputy Surveyor, under contract #514, dated Aug. 27, 1884 - (DCSO records Vol. 2 Page(s) 734)

Set post, 4" dia., 4 ft. long, with marked stone, 12" in ground, for qr. sec. cor. marked ¼ S on W face; from which Hemlock, 14" dia., bears S.25°W., 24 lks., mkd: ¼ S BT. Dogwood, 3" dia., bears S.36°E., 29 lks., mkd: ¼ S BT.

Douglas Co. Surveyors Office - Milo E. Godfrey - 1961 - C.S. File 49/143-2

Looked for & not found.

BLM Dependent resurvey by Wayne Rogers & Dale Bedell, Cadastral Surveyors, under Group #1392, surveyed Aug./Nov. 1987 - (DCSO records Vol. 48 Page(s) 18470)

Point for the ¼ sec. cor. of secs. 31 & 32, at proportionate distance; there is no remaining evidence of the orig. corner. Set an iron post, 28 long, 2½" dia., 22" in the ground with brass cap marked:

T 21 S R 6 W
 ¼
 S 31|S 32
 1987

from which

A fir, 4" dia., bears N.88°W., 21½ lks., mkd: X at breast height & BT at the base.

A maple, 12" dia., bears N.24°W., 67 lks., mkd: ¼ S31 BT.

No suitable trees available in secs. 32.

Deposit white "DEEP-1" magnetic marker at base of stainless steel post.

Carl Sweeden - For: Seneca Jones Timber Co - 9/2008 - M156-68

FOUND - 3" (1987) B.L.M. brass cap. Up 0.3'
16" dia. (Was 4") hemlock, bears N.85°W., 14.3' (N.88°W., 14.19') scar visible. Tag
12" dia. Maple stump. Rotted. Bears N.24°W., 44.0' (44.2')
12" dia. downed maple, rotted, tag on both sides, scar visible
New BTs- 11" dia. D.Fir. Bears N.23°E., 24.9', Scribed "W ¼ S 32 BT", tag, nail in bowl on west side
10" D.Fir, bears S.63°E., 10.9', scribed "W ¼ S 32 BT", tag, nail in bowl on south side.
Used 19°E dec.