

TOWNSHIP 21 RANGE 06 POINT IDENTIFIER # 240100

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 32; & 5 of T22-6

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by Gordon and Gardner, under Contract #52 dated Feb. 17, 1855 (DCSO records Vol. 2 Page(s) 694)

-----  
Set ¼ sec. post, from which  
A Fir 30" dia., bears N.45°W., 24 lks. dist.  
A Fir 24" dia., bears S.27°E., 20 lks. dist.

GLO survey by William R. Whipple, Deputy Surveyor, under Contract #514, dated Aug. 27, 1884 (DCSO records Vol. 2 Page(s) 702-03)

-----  
Found gr. sec. cor. gone. Reestablished the same by setting post, 4" dia., 4 ft. long, with mkd. stone, 12" in ground, mkd. ¼ S on N. face; from which  
Fir 24" dia., bears S.27°E., 20 lks. dist. mkd. ¼ S BT  
Fir 30" dia., bears N.47°W., 23 lks. dist. mkd. ¼ S BT

Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy - V. Tracy; Clete Putnam, crew - Sept. 1961 - C.S. File 49/143-85

-----  
Found - Fir tree, 36", N.47°W., 15.2 ft., uprooted and down, shows good axe scar at bottom. W. Haines says he found scribing about 6 years ago. (From position this is lying impossible to chop open now.)  
Badly burned Fir stump bears S.27°E., 13.2 ft. Too much gone to find scars or scribing.

Set Brass cap at cor. mkd: County Surveyors Office

T21S<sub>R6W</sub> ¼ S32  
T22S<sub>S 5</sub>

1961

New BTs -38" Fir S.23°E., 45.5 ft. mkd. ¼ S5 CS BT, all in one blaze.

30" Fir S.42°W., 47.7 ft. mkd. ¼ S5 CS BT, all in one blaze.

No trees near North of line.