

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 4 & 5

| Alias | Description |
|-------|-------------|
| Alias | Description |
| Alias | Description |
| Alias | Description |

| |
|---|
| <p>GLO survey by Wm. P. Wright, Deputy Surveyor, under contract #514, dated Aug. 27, 1884 - (DCSO records Vol. 2 Page(s) 733)</p> <p>-----</p> <p>A Fir, 4" dia., for qr. sec. cor., mkd ¼ S on W face; from which</p> <p> Fir, 8" dia., bears S.71°E., 28 lks., mkd: ¼ S BT.</p> <p> Fir, 6" dia., bears S.52°W., 8 lks., mkd: ¼ S BT.</p> |
| <p>Douglas Co. Surveyors Office - Milo E. Godfrey - 1962 - C.S. File 49/89-13</p> <p>-----</p> <p>Looked for & not found.</p> |
| <p>Dale Marx, LS 2196 - For: Western Pacific Timber Inc. - April/May 1987 - M105-45</p> <p>-----</p> <p>Searched for not found - Corner set established by single proportion.</p> <p>Set - 5/8"x30" iron rod, with yellow plastic cap marked "MARX ASSOCS".</p> |
| <p>Douglas Co. Surveyors Office - Randall W. Smith - Stephen J. Flause - March 1, 1988 - C.S. File 62/50-2</p> <p>-----</p> <p>Found - A 5/8" iron rod with plastic cap marked "Marx & Assocs." firmly set & protruding 5" above ground. A limited search was made for orig. corner & BTs. None were found.</p> <p>Set - A DCSO 2½" brass cap on a 1½" O.D. x 31" IP was set at referenced position of 5/8" IR. Cap & pipe protrudes 3" above ground. Cap mkd: "DOUGLAS COUNTY SURVEYORS T21S ¼ S5 S4 R6W 1988" Cap/pipe perpetuates Marx's point.</p> <p>5/8" IR set along northeast edge of DCSO cap, protruding 2" above ground.</p> <p>New BTs- 7" dia., Hemlock double blazed & scribed "¼ S5 CS BT" bears N.54°W., 22.1 ft.</p> <p>22" dia., D.Fir double blazed & scribed "¼ S5 CS BT" bears S.15½°W., 12.3 ft.</p> <p>5" dia., D.Fir double blazed & scribed "X BT" bears N.42°E., 22.7 ft.</p> <p>6" dia., D.Fir double blazed & scribed "¼ S4 CS BT" bears N.80°E., 35.8 ft.</p> <p>Corner lies on a steep north slope approx. 500 ft. north of an east-west ridge & approx 200 ft. SW of the convergence of two gullies.</p> |
| <p>continued next page</p> |

TOWNSHIP 21 RANGE 06 POINT IDENTIFIER # 300640

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 4 & 5

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Steven Ness - Oct. 14, 1994 - M 121 - 24 A&B

From narrative:

At the west $\frac{1}{4}$ corner of Sec. 4, we fd. the proportioned position established in survey M105-45 to be in error. We determined a proportioned position about 5 ft. South of the position from M105-45 & which position was remonumented by the Douglas Co. Surveyors Office. As this difference exceeds what I feel to be acceptable accuracy limits, I decided to monument our proportioned position for the West $\frac{1}{4}$ corner...

Set - 2"x36" I.P. with 2 $\frac{1}{2}$ " brass cap cemented to the top,
mkd:T21S R6W $\frac{1}{4}$ S5|S4 1994 RPLS 811
24" D.Fir, N.30°35'E. 29.0 to center, 28.95 to "W"
nail, scribed " $\frac{1}{4}$ S4 BT".
24" D.Fir, N.86°41'W. 32.8 to center, 31.97 to "W"
nail scribed " $\frac{1}{4}$ S5 BT".

Found - 2 $\frac{1}{2}$ " DCSO brass cap on 1 $\frac{1}{2}$ " I.P. N.8°45'35"E., 4.77
from set monument.
Fd. 5/8" I.R. w/yellow plastic cap mkd. "Marx &
Assoc." on the north side of the DCSO mon.

BTs found from set mon.

10" W.Hemlock, N.44°06'W. 24.7, two healed faces
24" D.Fir, S.19°44'W. 7.6, two healed faces
6" D.Fir, N.36°24'E. 26.8, two small partially
healed faces, some scribing visible.
8" D.Fir, N.73°06'E. 37.6', two healed faces