

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 4 & 9

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Wm. P. Wright, Deputy Surveyor, under contract #514, dated Aug. 27, 1884 - (DCSO records Vol. 2 Pages 732-3)

-----  
Set post, 4" dia., 4 ft. long, with marked stone, 12" in ground, for qr. sec. cor. marked ¼ S on N face; from which  
Fir, 36" dia., bears N.81°W., 54 lks., mkd: ¼ S BT.  
Fir, 36" dia., bears S.65°W., 28 lks., mkd: ¼ S BT.

Douglas Co. Surveyors Office - Milo E. Godfrey - 1962 - C.S. File 49/143-2

-----  
Looked for & not found.

Stephen Ness - For: Weyerhaeuser Co. - 10/1994 - M121-24 A&B

-----  
Not found.  
I made an extensive search for the South ¼ corner of sec 4. The original 1884 GLO survey notes called for a post & a marked stone at the corner position and two 36" firs as accessories. Also, the orig. notes placed the corner 1.32 chains east of a ridge top. From 1967 Weyerhaeuser aerial photos, I determined a search area, but could find no evidence of the post or stone nor a pattern of old stumps, or stump holes, that would fit the original calls to the 36" firs. This area had been logged some 50 to 80 years ago, so chances of finding the post or stone would be remote. However, evidence of the firs should still remain. In comparing the topo calls from the 1884 notes to the aerial photos, the west 1/2 mile is almost identical to the photos, but the east 1/2 mile topo calls miss two ridge crossings and a main draw. It is possible that this corner was "stubbed" and thus could be out of position in latitude. It is also possible that the corner was never set or that it was destroyed by logging as there is evidence of a "swing road" used for logging about 100 feet to the west of my search area. A search was also made, with hand compass and steel tape, from our closest traverse point for the CW 1/16 corner set in M105-45. Because of heavy logging debris and brush, we were unable to locate the monument, assuming it was not destroyed by logging.