

TOWNSHIP 21 RANGE 06 POINT IDENTIFIER # 400100

PRIMARY CORNER DESCRIPTION Sec. Cor. for 33 & 34; 3 & 4 of T22-6

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GL0 survey by Gordon and Gardner, under Contract #52 dated Feb. 17, 1855 (DCSO records Vol. 2 Page(s) 693)

Set post corner of secs. 3, 4, 33 and 34; from which
A Maple 8" dia., bears N.32°W., 68 lks. dist.
A Fir 24" dia., bears N.73°E., 36 lks. dist.
A Fir 10" dia., bears S.32°E., 58 lks. dist.
A Fir 10" dia., bears S.35°W., 48 lks. dist.

GL0 survey by William R. Whipple, Deputy Surveyor, under Contract #514, dated Aug. 27, 1884 (DCSO records Vol. 2 Page(s) 701)

Place where old cor. stood, one of the bearing trees standing. Reestablished the cor. by setting post, 6" dia., 4 ft. long, in ground 12", with mkd. stone mkd. T21S S34 on NE.; R6W S3 on SE.; T22S S4 on SW.; S33 on NW.; face, with 3 notches in E. and W. edges; from which
Fir 30" dia., N.73°E., 36 lks. dist. mkd. T21S R6W S34 BT.
Fir 10" dia., S.20°E., 60 lks. dist. mkd. T22S R6W S3 BT.
Fir 10" dia., S.40°W., 50 lks. dist. mkd. T22S R6W S4 BT.
Fir 10" dia., N.35°W., 70 lks. dist. mkd. T21S R6W S33 BT.

George Scroggin - Survey of Plat of Sunnydale Orchards - Aug. 6, 1914 - Plat Vol. 5 Page 20 A&B

Iron pipe.

Douglas Co Surveyors Office - Milo E Godfrey, Deputy - Vernon Tracy; Clete Putnam, crew - Sept/Oct 1961 - C.S. 49/143-5

Found - 1/2" I.Pipe.
28" W.Fir S.40°W., with rotten center and no scribing left visible, 29.0 ft. from I.P., rec. 35.0 ft. W.Haines says he has seen scribing on this tree.

No other trees found.

Set Brass cap at cor. mkd: County Surveyors Office

S 33 | S 34 T21-6W

S 4 | S 3 T22-6W

1961

New BTs -14" D.Fir N.17°E., 10.7 ft. mkd. T21S R6W S34 CSBT
10" Yew N.48°W., 49.4 ft. mkd. T21S R6W S33 CS BT.
26" D.Fir S.3°W., 37.3 ft. mkd. T22S R6W S3 CS BT.
15" D.Fir S.72°W., 30.4 ft. mkd. T22S R6W S4 CSBT.

(Cont. Next Page)

TOWNSHIP 21 RANGE 06 POINT IDENTIFIER # 400100

PRIMARY CORNER DESCRIPTION Sec. Cor. for 33 & 34; 3 & 4 of T22-6

Alias	Description
Alias	Description
Alias	Description
Alias	Description

Douglas Co. Surveyors Office - John M. Powell, Pete Earle; Lorraine Lewis; Virginia Yates (Laugen), Witnesses - Sept. 14, 1973 - C.S. File 56/38-1

Found - DCSO brass cap, properly mkd. in 1961, in corner of new fence.
14" D.Fir N.17°E., 10.7 ft., pitched over, scribing.
10" Yew N.48°W., 49.4 ft., scribing visible.
26" D.Fir (Grand Fir) S.3°W., 37.3 ft., now snag.
15" G.Fir S.72°W., 30.4 ft., scribe pitched over.
New BT - 8" Maple S.48°E., 10.5 ft., bark scribed with knife, "S3 CS BT".

Fd. and Used in BLM resurvey by Akin, Group #828, surveyed Oct. 1973 (DCSO records, Vol. 36 Pages 14991-92)

Douglas Co. Surveyors Office - Randall Smith and Stephen Flause, crew - Feb. 24, 1992 - C.S. File 64/24-3

Found - A 2½" dia. DCSO brass cap on a 1½" O.D. Iron pipe protruding 9" above ground.
14" now 10" dia. rotted 1½ ft. tall D.Fir stump, scribing visible "31 CS BT" bears N.17°E., 10.7 ft. (agrees w/rec).
26" now rotted Fir stump of indeterminable size, no blazes or scribing visible, bears S.3°W., 37.3 ft. (agrees w/rec)
15" now down and rotted D.Fir, no blazes or scribing visible, root hole bears S.72°W., 30.4 ft. (agrees w/rec).
10" now 12" dia. Yew with a partially healed double blaze, rotted scribe visible "T21S R5W S33" bears N.48°W., 49.4 ft. (agrees w/rec.)
8" now 13" dia. Maple with illegible bark scribing bears S.48°E., 10.5 ft. (agrees w/rec.)
New BTs - 13" dia. W.Fir double blazed and scribed "T22S R6W S4 CS BT" bears S.58°W., 38.8 ft.
13" dia. W.Fir double blazed and scribed "T22S R6W S3 CS BT" bears S.18½°E., 33.2 ft.
Corner lies at the intersection of a West & South running fence lines.

Fd. OK, Feb. 1994 - M 118-39

continued next page

TOWNSHIP 21 RANGE 06 POINT IDENTIFIER # 400100

PRIMARY CORNER DESCRIPTION Sec. Cor. for 33 & 34; 3 & 4 of T22-6

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Eugene Wobbe - Crew: Sean Lange & Matthew Ternyik - 7/7/2017
- C.S. File 65/95-47

-
- Found - 2½" brass cap (properly mkd) on 1½" iron post bent S.60°W., 0.7'. Corner falls at the corner of an old fence line running West and South from the corner.
 - 10" Yew now 12" with healed face fallen - stump hole bears N.48°W., 49.4' - 1961 BT.
 - 8" Maple now 16" markings illegible - bears S.48°E., 10.5' - 1973 BT.
 - 13" W.Fir now 24" with healed face bears S.17°E., 33.0' (Rec. S.18½°W., 33.2') - 1992 BT
 - 13" W.Fir now 18" with healed face bears S.61°W., 39.9' (Rec. S.58°W., 38.8') - 1992 BT
 - New - Set alum channel marker post with BLM land survey marker sign 3' west of corner.
 - Note - Bearings are based on 1973 BLM survey.