

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by Laban H. Wheeler, Under Contract #467 dated April 7, 1883 (DCSO records Vol. 2 Page(s) 559)

-----  
Set post 3" dia., 4 ft. long, 24" in ground for qr. sec. cor., marked ¼ S on W. face; from which  
A Fir 36" dia., bears N.35°W., 36 lks. dist. mkd. ¼ S BT.  
A Fir 24" dia., bears N.80°E., 27 lks. dist. mkd. ¼ S BT.

BLM Resurvey by Lytle; Norseth; Tillman; Bicknell; Gawron and Thielsen, Cadastral Engineers, under Group #304, Surveyed Aug. 1952/oct. 1954 - (DCSO records Vol. 30 Page(s) 12549)

-----  
Point for the ¼ sec. cor. determined from the original bearing trees;

A Fir 37" dia. bears N.80°E., 27 lks. mkd. ¼ S BT in bark.  
A Fir 35" dia. bears N.35°W., 36 lks. mkd. ¼ S BT in bark.

At the corner point

Set an iron post, 3 ft. long, 1" dia., 27" in the ground, with brass cap mkd:

¼  
S 36|S 31  
1952

from which

A Fir 50" dia., bears S.80°E., 70 lks. dist. mkd. ¼ S31 BT  
A Hemlock 22" dia., bears N.13°W., 82 lks. dist. mkd. ¼ S36 BT.

BLM Remonumentation of corner by Floyd Brooks and James Jolley, Cadastral Surveyors, under Group #'s 350 & 536, Surveyed May/June 1964 - (DCSO records Vol. 32 Page(s) 13527)

-----  
The ¼ sec. cor. established by Wheeler in 1883 and remonumented by Lytle in 1952, with an iron post 36" long, 1" dia., which has been bent over and nearly pulled out of the ground by logging equipment during a recent logging operation. The original bearing trees were wind thrown during a storm on Oct. 12, 1962, and are now uprooted and burned stumps with no marks remaining on them. One of the trees mkd. by Lytle in 1952 is in the same condition. The stumps have all been pushed out of position by logging equipment. The other bearing tree mkd. by Lytle in as follows:

A Hemlock snag 24" dia., bears N.13°W., 82 lks. dist., with a healed blaze.

At the corner point, at record bearing and distance from the Hemlock snag:

RESET the iron post 36" long, 1" dia., 28" in the ground with brass cap mkd:

¼  
S 36|S 31  
1952

(Cont. Next Page)

Alias	Description
Alias	Description
Alias	Description
Alias	Description

from which new bearing trees:  
A Hemlock 8" dia., bears N.16°E., 325 lks. mkd. ¼ S31 BT.  
A Maple 5" dia., bears S.71°E., 33 lks. mkd. ¼ S31 BT.  
These trees are the only ones available within a reasonable distance in the entire area.

BLM remonumentation by Aaron M. Graham, Cadastral Surveyor under Group #1000, surveyed May 1999/April 2000 - (DCSO rec. Vol. 54 Page(s) 20736)

-----

The ¼ sec. cor. of secs. 31 and 36, on the E. bdy. of the Tp. monumented with an iron post, 1" dia. firmly set, projecting 12" above the ground, with brass cap (properly) mkd. from which the remains of the original bearing trees  
A fir stump, 29" dia., bears N.80°E., 17.8 ft., no marks visible.  
A root hole, bears N.35°W., 23.8 ft., with fir log alongside, no marks visible.  
and new bearing trees  
A fir, 18" dia., bears N.51¼°E., 23.9 ft., mkd. ¼ S31 BT.  
A fir, 15" dia., bears S.84°W., 27.3 ft., mkd. ¼ S36 BT.

Gary Smithers - May 2005 - C.S. File 65/54-19

-----

Found - 1952 Brass Cap on Iron Pipe firmly set with a steel post alongside.  
28" Fir stump, N.80°E., 18.0 ft., rotted with old tag, no markings. 1952  
35" Fir, N.35°W., 23.7 ft., has fallen over. 1952  
1964 Bearing Trees are gone  
17" D.Fir, S.84°W, 27.3 ft., with healed face & BT tag. 2000  
20" D.Fir, N.52°E., 23.9 ft., with healed face & BT tag. 2000  
New BT - 15" D.Fir, S.57°E., 21.4 ft. to spike set side center, scribed "T21 R7 ¼ S31 BT", with BT tag.  
17" D.Fir, S.22°W., 26.6 ft to spike set side center, scribed "T21 R8 ¼ S36 BT", with BT tag.

Dependent resurvey by Edith M Forkner, Cadastral Surveyor, under Group #2114, surveyed Sept. 2005/Oct. 2006 - (DCSO records Vol. 55 Page(s) 21627)

-----

The ¼ sec. cor. of secs. 31 & 36, monumented with an iron post, 1" dia., firmly set, projecting 12" above ground, with brass cap (properly) mkd.  
from which the remains of the original bearing trees  
continued next page

TOWNSHIP 21 RANGE 07 POINT IDENTIFIER # 100140

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 31; & 36, T21-8

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

A decayed fir stump, 27" dia., bears N.80°E., 17.8 ft., no marks visible.  
A roothole bears N.35°W., 23.8 ft., with a down fir, 35" dia., alongside, no marks visible.  
and the bearing trees mkd. by Graham in 1999-2000  
A fir, 20" dia., bears N.51¼°E., 23.9 ft., with a healed blaze.  
A fir, 17" dia., bears S.84°W., 27.3 ft., with a healed blaze.  
and the bearing trees mkd. by Gary T. Smither, in 2005  
A fir, 15" dia., bears S.72°E., 21.9 ft., with scribe marks 21 R7 ¼ S31 BT visible on partially healed blaze.  
A fir, 18" dia., bears S.19¾°W., 27.8 ft., with scribe marks S36 BT and other illegible marks visible on partially healed blaze.  
A steel fence post is alongside the cor.