

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 17 & 20

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by Wm. P. Wright, Deputy Surveyor, under contract #514, dated Aug. 27, 1884 - (DCSO records Vol. 2 Page(s) 671)

Set post, 4" dia., 4 ft. long, with marked stone, 12" in ground, for qr. sec. cor. marked ¼ S on N face; from which Cedar, 36" dia., bears South, 6 lks., mkd: ¼ S BT.
Maple, 6" dia., bears N.80°W., 12 lks., mkd: ¼ S BT.

BLM dependent resurvey by Donald R. Beck, Cadastral Surveyor, under group #655, surveyed Sept./Oct. 1967 - (DCSO records Vol. 34 Page(s) 14163-4)

The ¼ sec. cor. of secs. 17 & 20 determined at the record bearing & distance from the remaining orig. BT:

A cedar snag, 50" dia., bears South 6 lks., with no marks visible on rotted blaze.

At the corner point

Set an iron post, 28" long, 2½" dia., 24" in the ground, with brass cap marked:

T 21 S R 7 W

¼ $\frac{S\ 17}{S\ 20}$
1967

from which

A fir, 35" dia., bears N.20°W., 70 lks., mkd: ¼ S17 BT.

A maple, 18" dia., bears S.35°W., 29 lks., mkd: ¼ S20 BT.

Dependent resurvey by Edith M Forkner, Cadastral Surveyor, under Group #2114, surveyed Sept. 2005/Oct. 2006 - (DCSO records Vol. 55 Page(s) 21625-6)

The ¼ sec. cor. of secs. 17 and 20, monumented with an iron post, 2½" dia., firmly set, projecting 5" above ground, with brass cap (properly) mkd.

from which the remains of an original bearing tree

A roothole bears South, 4.0 ft., with a down decayed cedar, 45" dia., alongside, no marks visible and a bearing tree mkd. by Beck in 1967

A maple, 24" dia., bears S.35°W., 17.4 ft., no marks visible. (Record, 19.1 ft.)

and a new bearing tree

A hemlock, 25" dia., bears N.70½°W. 40.0 ft. mkd. ¼ S17 BT
Corner is located N., 45 ft. of Halfway Creek, 15 ft. wide, course W and S., 90 ft. of Halfway Creek Road, graveled surface, 10 ft. wide, bears N.65°W. and S.80°E.