

PRIMARY CORNER DESCRIPTION Cor. of Secs. 33 & 34 only, (South)

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Gordon and Gardner, under Contract #52 dated Feb. 17, 1855 (DCSO records Vol. 2 Page(s) 632)

Set post corner of secs. 3, 4, 33 and 34; from which
Maple 8" dia., bears S.34°W., 22 lks. dist.
Dogwood 4" dia., bears S.66°E., 23 lks. dist.
Maple 10" dia., bears S.64°E., 25 lks. dist.
Dogwood 3" dia., bears N.50°W., 57 lks. dist.

Original, Laban H. Wheeler, Under Contract #467 dated April 7, 1883 (DCSO Records, Volume 2 Page 649)

Found all evidence of corner and trees gone, having been destroyed by fire. Reestablish the same by setting a post, 6" dia., 4 ft. long, with marked stone, 12" in ground, marked T21S S34 on NE.; R7W S3 on SE.; T22S S4 on SW.; S33 on NW. faces; with 3 notches on E. & W. edges; from which
Fir 20" dia., bears N.62°W., 23 lks. dist. mkd. T21S R7W S33 BT.
Fir 20" dia., bears S.40°E., 43 lks. dist. mkd. T22S R7W S3 BT.
Cedar 12" dia., bears S.9°W., 49 lks. dist. mkd. T22S R7W S4 BT.
Maple 12" dia., bears N.31°E., 39 lks. dist. mkd. T21S R7W S34 BT.

GLO survey by Carl S. Nicklin, Deputy Surveyor, under Contract #664 dated May 23, 1896 (DCSO records Vol. 4 Page(s) 1545-46)

The sec. cor. of 3, 4, 33 and 34, which is a post 30" above ground, the bearing trees do not agree with the description furnished by the Surveyor General, their bearings and distances from the cor., varying materially from that description; at same point, I reestablish this cor. as follows:
Set a Fir post, 3 ft. long, 4" sq., 24" in the ground, for cor. of secs. 33 and 34, T21S R7W, mkd. T21S S34 on NE.; and R7W S33 on NW. faces; with 3 notches on E. and W. edges, from which
A Maple 10" dia., bears N.33°E., 38 lks. dist. mkd. T21S R7W S34 BT.
A Fir 16" dia., bears N.60°W., 28 lks. dist. mkd. T21S R7W S33 BT.

(Cont. Next Page)

TOWNSHIP 21 RANGE 07 POINT IDENTIFIER # 400100

PRIMARY CORNER DESCRIPTION Sec. cor. for 33 & 34 only, (South)

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Wilford N. Haines - For: Harold Woolley - March 1957 - M 4-52
and Field Book, H-178

Found - Original corner.
Set 1" x 36" T rod at corner point with brass cap inscribed
"Wilford N. Haines Survey Point #239"

Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy - V.
Tracy & C Putnam, crew - May/June 1962 - C.S. File 52/14-109

Found - Haines T Iron and cap at corner.
Maple now 24", N.33°E., 25.1 ft. reverse scribing
visible on wood grown against old face, tree
hollow and one side rotted away.
W.Fir now 40" N.60°W., 18.5 ft., hollow and SE side
rotted away, no scribing seen.
No trace of Fir BT to SE.
Remnant of Cedar stump, S.9°W., 32.3 ft., apparently
one of Wheeler's trees, 1883 survey.
New BTs -31" D.Fir N.20°W., 38.5 ft. mkd. T21S R7W S33 CSBT
16" D.Fir N.54°E., 66.9 ft. mkd. T21S R7W S34 CSBT

David Edwards - For: Seneca Jones - 1/2002 - M 136-69 & C.S.
File 65/41-3

Found - T-iron per M4-52
All BTs down or stumps
Set - Steel posts North, South, East, & West. All at 5.0 ft

Found and used by T. Baker, Jan. 2003 - M141-58