

TOWNSHIP 21 RANGE 08 POINT IDENTIFIER # 140400

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 18 & 19

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Wm. P. Wright, Deputy Surveyor, under contract #486, dated Aug. 1, 1883 - (DCSO recs. Vol. 2 Page(s) 878)

Set post 4" dia., 4 ft. long on mound of stone 18" high 3½ ft. sq. at base for ¼ sec. cor. marked ¼ S on N face.

BLM dependent resurvey by Norman D. Price, Cadastral Eng. & Geo. F. Rigby, Assoc. Cadastral Eng., under group #282, surveyed May/Aug. 1945 - (DCSO records Vol. 27 Page(s) 11422)

Proportional measurement
Set an iron post, 3' long, 1" dia., 28" in the ground, for ¼ sec. cor., with brass cap marked:

¼ $\frac{S\ 18}{S\ 19}$
1945

from which

- A fir, 28" dia., bears N.86½°E., 109 lks., mkd: ¼ S18 BT.
- A fir, 30" dia., bears S.29½°E., 54 lks., mkd: ¼ S19 BT.

Rob Ward - For: Roseburg Resources Co. - April 2002 - M140-10

The position of this corner was not held. "This corner was found to be 20.06' N.36°17'29"E from a single proportioned position based on the 1884 GLO record. The BLM was contacted and requested to review the as tied position of the 1945 ¼ corner. A letter indicating a corrective dependent resurvey would be initiated was issued on February 19, 2002, by the BLM Our client requested this corner be set in conjunction with this survey." - per narrative

Set - 5/8" X 24" rebar in sandstone with 2½" aluminum cap marked as shown: T21S R8W

¼ $\frac{S\ 18}{S\ 19}$
2002
LS1091

- 22" D.Fir bears N.79°W. 40.8' blazed/scribed:¼ S18 BT
- 20" D.Fir bears S.76½°W. 15.5' blazed/scribed:¼ S19 BT
- 20" D.Fir bears S.56¼°E 13.3' blazed/scribed:¼ S19 BT
- 2½" GLO brass cap dated 1945 bears N.36°17'29"E. 20.06'

continued next page

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 18 & 19

Alias	Description

BLM dependent resurvey by Aaron M. Graham, Cadastral Surveyor, under Group No. 2011, surveyed Dec. 2002/Feb. 2003 - (DCSO records Vol. 54 Page(s) 20773-4)

The ¼ sec. cor. of secs. 18 & 19, reestablished by proportionate measurement by Ward, in 2002, & is accepted as the corner; monumented with an iron rod, 5/8" diam., firmly set, projecting 3" above the ground, with aluminum cap (properly) mkd.

from which bearing trees mkd. by Ward

A fir, 21" dia., bears S.55¾°E., 13.6 ft., with scribe marks ¼ S19 BT visible on partially healed blaze.

A fir, 22" dia., bears S.75¼°W., 15.5 ft., with scribe marks ¼ S19 BT visible on partially healed blaze.

A fir, 23" dia., bears N.78¾°W., 40.4 ft., with scribe marks ¼ S18 BT visible on partially healed blaze.

From this point, the ¼ sec. cor. of secs. 18 & 19, erroneously reestablished by Price and Rigby in 1945, bears N.36°01'15"E., 20.07 ft.; monumented with an iron pipe, 1" dia., firmly set, projecting 14" above the ground, with brass cap mkd. as described in the official record. From which the remains of the bearing trees by Price and Rigby.

A decayed fir stump, size indeterminate bears N. 86½° E., 71.9 ft., no marks visible.

Remark the brass cap to now read AM 20.1 FT TO COR 2003 and an arrow pointing to the corner.