

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 6 & 7

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

GLO survey by Wm. P. Wright, Deputy Surveyor, under contract #486, dated Aug. 1, 1883 - (DCSO recs. Vol. 2 Page(s) 883)

Set post 4" dia., 4 ft. long on mound of stone 18" high 3¼ ft. base for ¼ sec. cor. mkd: ¼ S on N face.

BLM dependent resurvey by Norman D. Price, Cadastral Eng. & Geo. F. Rigby, Assoc. Cadastral Eng., under group #282, surveyed May/Aug. 1945 - (DCSO records Vol. 27 Page(s) 11428)

Proportional measurement
Set an iron post, 3' long, 1" dia., 28" in the ground, for ¼ sec. cor., with brass cap marked:
$$\frac{1}{4} \begin{array}{c} S \ 6 \\ S \ 7 \end{array}$$

1945
from which
A fir, 60" dia., bears N.59°W., 48 lks., mkd: ¼ S6 BT.
A fir, 60" dia., bears N.84°E., 127 lks., mkd: ¼ S7 BT.

Survey by Donald Bentz, LS #839 - For: International Paper Co. - Oct. 1989 - M 101-62

Found - 1945 USGLO brass cap
New BTs- 13" D.Fir bears N.8°W., 15.4 ft. scribed.
14" D.Fir bears S.4°W., 8.9 ft. scribed.
6' alum. post with sign facing IP property with buried magnetic marker bears S.4°W., 8.9 ft.

Gary Smithers - Dec. 2001 - C.S. File 65/42-7

Found - 1945 brass cap on iron pipe firmly set with alum. post driven alongside the brass cap.
1945 51" Fir stump burnt & rotting, N.59°W., 48 lks., no markings.
1945 60" Fir stump rotting, N.84°E., 127 lks., no markings.
15" Fir, S.4°W., 8.9 ft. with healed face & BT tag.
19" Fir, N.8°W., 15.4 ft. with healed face & BT tag.
New BTs- 13" D.Fir, S.42°E., 6.0 ft. to spike driven in side center, marked "T21 R8 ¼ S7 BT", with BT tag.
10" D.Fir, N.56°E., 11.4 ft. to spike driven in side center, marked "T21 R8 ¼ S6 BT", with BT tag.