

TOWNSHIP 21 RANGE 08 POINT IDENTIFIER # 200200

PRIMARY CORNER DESCRIPTION W C Secs 29, 30, 31, & 32

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Wm. P. Wright, Deputy Surveyor, under contract #486, dated Aug. 1, 1883 - (DCSO recs. Vol. 2 Page(s) 873)

Fir, 24" dia., for cor. to secs. 29, 30, 31, & 32 marked T21S, S29 on NE, R8W, S32 on SE, S31 on SW, S30 on NW face with 5 notches on E & 1 on S edge from which:

- Fir, 30" dia. bears N.40°E., 45 lks. mkd: T21S R8W S29 BT.
- Fir, 25" dia. bears S.65°E., 18 lks. mkd: T21S R8W S32 BT.
- Fir, 30" dia. bears S.30°W., 26 lks. mkd: T21S R8W S31 BT.
- Fir, 36" dia. bears N.65°W., 51 lks. mkd: T21S R8W S30 BT.

BLM dependent resurvey by Norman D. Price, Cadastral Eng. & Geo. F. Rigby, Assoc. Cadastral Eng., under group #282, surveyed May/Aug. 1945 - (DCSO records Vol. 27 Page(s) 11414 & 11416)

The cor. of secs. 29, 30, 31, & 32, a fir, 32" dia., with partial scribe marks on NE., SE., SW., & NW. side, on bark; from which:

- A Fir, 38" dia., bears N.40°E., 48 lks., with partial scribe marks on bark. (OBT)
- A burnt Fir stump, 36" dia., bears S.65°E., 21 lks., on which no marks remain. (OBT)
- A burnt Fir stump, 36" dia., bears S.23°W., 30 lks., on which no marks remain. (OBT)
- A Fir, 48" dia., bears N.62½°W., 54 lks., with partial scribe marks on bark. (OBT)

N.0°25'E., 0.10 chains

Set an iron post, 3 ft. long, 2" dia., 28" in the ground, for witness corner to the cor. of secs. 29, 30, 31, & 32, with brass cap marked:

W C
T21S R8W
S 30 S 29
S 31 S 32

1945

from which

- A Fir, 38" dia., bears N.49°E., 40 lks., an old BT which I re-blaze & re-mark: WC T21S R8W S29 BT.
- A Fir, 44" dia., bears S.28°E., 67 lks., mkd: WC T21S R8W S32 BT. (New BT)
- A Fir, 40" dia., bears S.79°W., 61 lks., mkd: WC T21S R8W S31 BT. (New BT)
- A Fir, 48" dia., bears N.72½°W., 52 lks., mkd: WC T21S R8W S30 BT.

continued next page

TOWNSHIP 21 RANGE 08 POINT IDENTIFIER # 200200

PRIMARY CORNER DESCRIPTION W.C. Secs 29, 30, 31, & 32

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Douglas Co. Surveyors Office - Vernon "Ray" Tracy - Jack Heritage - V. Perron - July 1973 - C.S. File 56/34-3

Found - 1945 GLO brass cap properly mkd., in place, firmly set.
OBTs are now burned stumps & badly decayed. No scribe found on blazes due to burn.
New BTs- 9" D.Fir, S.22½°W., 31.0 ft. mkd: WC T21S R8W S31 CS BT.
8" D.Fir, S.7°E., 22.9 ft. mkd: WC T21S R8W S32 CS BT.
6" D.Fir, N.72°E., 14.0 ft. mkd: WC T21S R8W S29 CS BT.
9" D.Fir, N.41°W., 29.2 ft., mkd: WC T21S R8W S30 CS BT.
Note - This WC lies 6.6 ft. N.0°25'E., of true corner as recorded in Gov't. field notes.

Gary Smithers - Feb. 2004 - C.S. File 65/49-21

Found - 1945 Brass Cap on Iron Pipe firmly set. Original 24" Fir corner tree is rotted with old tag but no marks and lies S.0°25'W., 6.6 ft. We Set a 6 foot galvanized steel fence post alongside the old corner tree with top Painted red.
Old Bearing Trees Taken in Original GLO Survey
48" rotted Fir Stump, N.62½°W., 54 links, no marks, with old Bearing Tree Tag. This bearing & dist. are from the original corner tree.
All other Original Bearing Trees are gone.
Old Bearing Trees Taken in 1945 by GLO:
44" rotted Fir Stump, S.28°E., 67 links, no marks. This bearing and distance are from the WC.
48" rotted Fir Stump, N.72½°W., 52 links, no marks. This bearing and distance are from the WC.
All other 1945 Bearing Trees are gone.
Bearing trees Taken in 1973 by Douglas County Surveyor:
19" D. Fir, S.22½°W., 31.0 ft from WC, with healed face and aluminum tag
18" D. Fir, S.7°E., 22.9 feet from WC, with healed face and aluminum tag
15" D. Fir, N.72°E., 14.0 feet from WC, with healed face and aluminum tag.
23" D. Fir, N.41°W., 29.2 ft. from WC, with healed face and aluminum tag.