

PRIMARY CORNER DESCRIPTION So. 1/4 Cor. Sec. 32 only

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by W.H. Byars, Deputy Surveyor under contract # 376 survey dated Jan. 22, 1881 (DCSO records Vol. 2 Page(s) 837)

Set Fir post for ¼ sec. corner, from which
A Fir tree bears N.41°E., 60 lks. 30" diam.
A Fir tree bears S.80°E., 50 lks. 24" diam.

GLO resurvey by Norman D. Price, Cadastral Engineer and Geo. Rigby, Assoc. Cadastral Engineer, under Group #282, surveyed May/Aug. 1945 (DCSO records Vol. 27 Page(s) 11376)

Point for the ¼ sec. cor. of sec. 32 only, determined at the record measurement from each of the old bearing trees.
At point for corner,
Set an iron post 3 ft. long, 1" dia., 28" in the ground, for ¼ sec. cor. of sec. 32 only, with brass cap mkd: ¼ S 32
1945

from which
A stump hole bears N.42°E., 60 lks. dist. which is the remains of an old bearing tree.
A Fir 48" dia., bears S.73°E., 50 lks. dist. mkd. on bark ¼ S BT. (An old bearing tree which I do not deface because it is the only remaining apparent evidence of the old corner.)
A Fir 32" dia., bears N.56¼°E., 186 lks. dist. mkd. ¼ S32 BT. (New BT)
A Fir 28" dia., bears N.87½°E., 222 lks. dist. mkd. ¼ S32 BT. (New BT)
This ¼ sec. cor. is located in the head of a ravine, course N., about 1 ch. N. of the ridge which is the divide bet. Weatherly Creek and the Umpqua River, at edge of burn bears NE and SW.

BLM resurvey by Floyd A. Brooks and James E. Jelley, Cadastral Surveyors, under Group #'s 514 and 350, surveyed June 1963/March 1965 (DCSO records Vol. 33 Page(s) 13678)

The ¼ sec. cor. of sec. 32 only, monumented with an iron post 1" dia., 10" above ground, firmly set, with properly mkd. BC. from which an original bearing tree,
A sawed Fir stump 50" dia., bears S.73°E., 50 lks. dist. with only bottom of blaze remaining.
and bearing trees mkd. by Price:
A sawed Fir stump 40" dia., bears N.56¼°E., 186 lks. dist. with fragmentary scribe marks visible on open and burned blaze.

(Cont. Next Page)

TOWNSHIP 21 RANGE 08 POINT IDENTIFIER # 240100

PRIMARY CORNER DESCRIPTION So. 1/4 Cor. Sec. 32 only

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

A down Fir 35" dia., bears N.87½°E., 222 lks. dist. with fragmentary scribe marks visible on open and burned blaze.
and a new bearing tree
A burned Fir snag 36" dia., bears N.29 3/4°E., 141 lks. dist. mkd. ¼ S32 BT.
Set a 7 ft. steel fence post 2 ft. in the ground alongside the iron post.
Cor. is located about one chain N. of ridge.

BLM remonumentation by Aaron M. Graham, Cadastral Surveyor and Michael O. Jones Surveying Technician, under Group #2199, surveyed April 2008/April 2009 - (DCSO rec. Vol. 56 Pg 21933)

The ¼ sec. cor. of sec. 32 only, perpetuated by Price & Rigby in 1945; monumented with an iron post, 1" dia., firmly set, projecting 6" above ground, with a brass cap (properly) mkd. from which the remains of an original bearing tree
A fir stump, 50" dia., bears S.73°E., 33.0 ft., no marks visible.
and the bearing trees mkd. by Price and Rigby in 1945
A fir stump, 40" dia., bears N.56¼°E., 122.8 ft., with illegible scribe marks visible on open blaze.
A roothole, bears N.87½°E., 146.5 ft., alongside of which is a down fir, 35" dia., no marks visible.
and new bearing trees
A fir, 19" dia., bears N.38°E., 3.2 ft., mkd. ¼ S32 BT.
A fir, 16" dia., bears S.45°E., 19.9 ft., mkd. X BT.
A steel fence post is alongside the cor.