

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 8 & 17

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Wm. P. Wright, Deputy Surveyor, under contract #486, dated Aug. 1, 1883 - (DCSO recs. Vol. 2 Page(s) 879)

 Set post 4" dia., 4 ft. long with marked stone 12" in ground for 1/4 sec. cor. marked 1/4 S on N face from which:
 Fir, 16" dia., bears N.10°E., 19 lks., mkd: 1/4 S BT.
 Fir, 20" dia., bears S.24°W., 27 lks., mkd: 1/4 S BT.

BLM dependent resurvey by Norman D. Price, Cadastral Eng. & Geo. F. Rigby, Assoc. Cadastral Eng., under group #282, surveyed May/Aug. 1945 - (DCSO records Vol. 27 Page(s) 11424)

 Proportional measurement
 Set an iron post, 3' long, 1" dia., 28" in the ground, for 1/4 sec. cor., with brass cap marked:

$$\frac{1}{4} \frac{S \ 8}{S \ 17}$$
 1945
 from which
 A fir, 36" dia., bears N.4½°E., 65 lks., mkd: 1/4 S8 BT.
 A fir, 22" dia., bears S.18°W., 22 lks., mkd: 1/4 S17 BT.

BLM remonumentation of certain orig. corner points by Wm. W. Glenn & James E. Jelley, Cadastral Surveyors, under group #s 350 & 635, surveyed April/May 1967 - (DCSO records C.S. File 65/27-1)

 The 1/4 sec. cor. of secs. 8 & 17, monumented with an iron post, 1" dia., firmly set, projecting 8" above ground, with brass cap properly marked,
 from which bearing trees marked in 1945
 A fir, 42" dia., bears N.4½°E., 65 lks., no marks remaining on burned blaze. Rescribed 1/4 S8 BT on new blaze.
 A root hole, bears S.18°W., 22 lks., with a down fir alongside, 22" dia., no marks remaining on burned blaze.
 and a new BT
 A fir, 7" dia., bears South 31 lks., mkd: 1/4 S17 BT.
 Set a 6' steel fence post alongside the iron post.

Gary Smither - 2/2005 - C.S. File 65/54-8

 Found - 1945 BLM Brass Cap on Iron Pipe firmly set with a steel fence post driven alongside the Brass Cap.
 continued next page

TOWNSHIP 21 RANGE 08 POINT IDENTIFIER # 240500

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 8 & 17

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

40" Fir stump, N.4½°E, 42.9 ft (rec. 65 links) with rotted out face & no markings with old BT tag.
21" D.Fir, South, 20.4 ft (rec. 31 lks), with healed face & BT tag.
New - 14" D.Fir, S.65°W., 11.2 ft to spike side center, scribed T21 R8 ¼ S17 BT and BT tag.
13" D.Fir, N.18°W., 21.4 ft to spike side center, scribed T21 R8 ¼ S8 BT and BT tag.
12" D.Fir, N.66°E., 21.3 ft to spike side center, scribed T21 R8 ¼ S8 BT and BT tag.

Ronald L Rice - OCT. 2016 - Oxbow Timber 1 LLC - M172-76

Found - GLO bras cap dated 1945
40" Rotted D.Fir stump bears N.86½°W. 143.9' no mks.
19" Maple bears N.82°E., 14.9', healed face.
30" D.Fir bears N.21°W., 64.0', healed face.
Rec. 15" D.Fir bearing S.77°W. down out of position.
Steel post adjacent to corner.