

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 5 & 8

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by Wm. P. Wright, Deputy Surveyor, under contract #486, dated Aug. 1, 1883 - (DCSO recs. Vol. 2 Page(s) 882)

Fir, 5" dia., for 1/4 sec. cor. marked 1/4 S on N face from which:

Fir, 8" dia., bears North 4 lks., mkd: 1/4 S BT.

Fir, 6" dia., bears S.10°W., 5 lks., mkd: 1/4 S BT.

BLM dependent resurvey by Norman D. Price, Cadastral Eng. & Geo. F. Rigby, Assoc. Cadastral Eng., under group #282, surveyed May/Aug. 1945 - (DCSO records Vol. 27 Page(s) 11427)

Proportional measurement

Set an iron post, 3' long, 1" dia., 28" in the ground, for 1/4 sec. cor., with brass cap marked:

1/4 $\frac{S}{S}$
5
8
1945

from which

A fir, 40" dia., bears N.11 1/2°W., 123 lks., mkd: 1/4 S5 BT.

A fir, 40" dia., bears N.86 1/2°W., 218 lks., mkd: 1/4 S8 BT.

Fd. Ok on BLM remonumentation of certain orig. corner points by Wm. W. Glenn & James E. Jelley, Cadastral Surveyors, under group #s 350 & 635, surveyed April/May 1967 - (DCSO records C.S. File 65/27-1) ** also set a 6 ft. steel fence post alongside the iron post.**

Gary Smithers - Jan. 2002 - C.S. File 65/42-5

Found - 1945 brass cap on iron pipe firmly set. Set 6 ft. galvanized steel post alongside the brass cap.
1945 40" Fir, N.11 1/2°W., 123 lks., is gone.
1945 40" rotting Fir stump, N.86 1/2°W., 218 lks., no markings.

New BTs- 15" Maple, N.82°E., 14.9 ft. to spike driven in side center, marked "T21 R8 1/4 S5 BT", with BT tag.
24" D.Fir, N.21°W., 64.0 ft. to spike driven in side center, marked "T21 R8 1/4 S5 BT", with BT tag.
15" D.Fir, S.77°W., 70.9 ft. to spike driven in side center, marked "T21 R8 1/4 S8 BT", with BT tag.
14" Alder, S.39°E., 30.5 ft. to spike driven in side center, marked "T21 R8 1/4 S8 BT", with BT tag.