

PRIMARY CORNER DESCRIPTION So. Sec. cor. for 32 & 33 only

Alias	Description
Alias	Description
Alias	Description
Alias	Description

<p>and a new bearing tree, A Fir 23" dia., bears N.47°E., 66 lks. dist. mkd. T21S R8W S33 BT.</p>
<p>Douglas County Surveyors Office - Randall Smith & Stephen Flause - Mar. 13, 1997 - C.S. 64/71-20 -----</p> <p>Fd - 2½" dia. Brass cap on a 2" O.D. Iron pipe, protrudes 12" above ground. (1945). No OBT's Found 36" dia. now 38" dia. down D.Fir, bears N.45½°E., 35' (agrees with 1965 renewal). 6" now 18" dia. 2½' High Cedar stump with a healed blaze, bears N.70°W., 36.3' (agrees with 1965 renewal). 23" now 30" dia. D.Fir with a fully healed single blaze, bears N.53°E., 43.6' (rec. N.47°E., 43.6' possible compass reading error) 1965.</p> <p>New BTs- 20" dia. W.Fir double blazed and scribed "T21S R8W S32 CS BT", bears N.47°W., 14.6'. 10" dia. Maple double blazed and scribed "T21S R8W S33 CS BT", bears N.60°E., 20.2'. 16" dia. W.Fir double blazed and scribed "T21S R8W S33 CS BT", bears N.80°E., 69.3'. Corner lies on a steep southerly slope in a slide area.</p>
<p>Gary Smithers - Feb. 2004 - C.S. File 65/49-23 -----</p> <p>Found - 1945 Brass Cap on Iron Pipe firmly set. We set a 6 ft. galvanized steel fence post alongside with top painted red.</p> <p>Old Bearing Trees Taken in 1945 to Witness Corner by GLO: 38" D.Fir is down, N.45½°E., 35 ft with healed face. 18" rotted Cedar Stump, N.70°W., 36.3 ft no marks, no tag. 31" D.Fir Snag, N.53°E., 43.6 ft with healed face and tag.</p> <p>Bearing Trees taken in 1997 by Douglas County Surveyor: 22" W.Fir, N.47°W., 14.6 ft with visible scribe and aluminum tag. 11" Maple, N.60°E., 20.2 ft with healed face and aluminum tag. 17" W.Fir, N.80°E., 69.3 ft with healed face and aluminum tag.</p>