

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 16 & 17

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

GLO survey by Wm. P. Wright, Deputy Surveyor, under contract #486, dated Aug. 1, 1883 - (DCSO recs. Vol. 2 Page(s) 868-9)  
-----  
Set post 4" dia., 4 ft. long with marked stone 12" in ground for 1/4 sec. cor. marked 1/4 S on W face raised mound of stone along side.  
No witness trees near.

BLM dependent resurvey by Norman D. Price, Cadastral Eng. & Geo. F. Rigby, Assoc. Cadastral Eng., under group #282, surveyed May/Aug. 1945 - (DCSO records Vol. 27 Page(s) 11408)  
-----  
Proportional measurement  
Set an iron post, 3 ft. long, 1" dia., 28" in the ground, for 1/4 sec. cor., with brass cap marked: 1/4  
S 17|S 16  
1945 from which  
A Fir, 34" dia., bears S.37 1/2°E., 68 lks., mkd: 1/4 S16 BT.  
A Hemlock, 46" dia., bears S.60°W., 47 lks., mkd: 1/4 S17 BT

BLM remonumentation of certain orig. corner points by Wm. W. Glenn & James E. Jelley, Cadastral Surveyors, under group #s 350 & 635, surveyed April/May 1967 - (DCSO records C.S. File 65/27-1)  
-----  
The 1/4 sec. cor. of secs. 16 & 17, monumented with an iron post, 1" dia., firmly set, projecting 6" above ground, with brass cap properly mkd, from which the remaining BT mkd. in 1945:  
A Fir stump, 34" dia., bears S.37 1/2°E., 68 lks., no marks remaining on burned blaze. Rescribed 1/4 S16 BT on new blaze.  
and a new BT:  
A sawed Fir stump, 36" dia., bears N.34°W., 95 lks., mkd: 1/4 S17 BT.

Ronald Rice, Ward NW INC. - For: Roseburg Resources Co. - Oct. 2002 - M141-12  
-----  
Found - 1945, 2 1/2" GLO brass cap w/the following accessories;  
48" X 3' D.Fir stump bears S60°W., 31 ft  
32" X 7' D.Fir stump bears S.37 1/2°E. 44.9 ft (visible scribing)  
New BTs- 12" D.Fir bears S.38°E, 14.5 ft (scribed 1/4 S16 BT)  
14" D.Fir Bears S.14°W, 7.0 ft (scribed 1/4 S17 BT)  
14" D.Fir Bears N.37°W, 22.6 ft (scribed 1/4 S17 BT)  
9" D.Fir Bears N.41°E, 22.4 ft (scribed 1/4 S16 BT)

TOWNSHIP 21 RANGE 08 POINT IDENTIFIER # 300440

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 16 & 17

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Ronald L Rice - OCT. 2016 - Oxbow Timber 1 LLC - M172-76

-----

Found - 1945 GLO brass cap  
60" D.Fir stump bears S.9°E., 40.9', rotted face.  
72" D.Fir stump bears S.52°W., 68.6', rotted face.  
18" D.Fir bears S.60°W., 34.6', healed face.  
15" D.Fir bears N.7½°W., 4.3', healed face.  
12" D.Fir bears N.50½°E., 25.6', healed face.  
12" D.Fir bears S.45°E., 35.3', healed face.  
Steel post adjacent to corner.