

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 4 & 9

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Wm. P. Wright, Deputy Surveyor, under contract #486, dated Aug. 1, 1883 - (DCSO recs. Vol. 2 Page(s) 871)

Set post 6" dia., 4 ft. long with marked stone 12" in ground for 1/4 sec. cor. marked 1/4 S on N face from which:

Cedar, 28" dia., bears North, 28 lks., mkd: 1/4 S BT.

Fir, 16" dia., bears S.10°W., 19 lks., mkd: 1/4 S BT.

BLM dependent resurvey by Norman D. Price, Cadastral Eng. & Geo. F. Rigby, Assoc. Cadastral Eng., under group #282, surveyed May/Aug. 1945 - (DCSO records Vol. 27 Page(s) 11412)

The 1/4 sec. cor., the locus of which is determined at the record bearing & dist. from each of the old BTs.

At point for corner,

Set an iron post, 3 ft. long, 1" dia., 28" in the ground, for 1/4 sec. cor., with brass cap marked: 1/4 $\frac{S\ 4}{S\ 9}$

1945

from which

A fallen Cedar, 50" dia., bears North, 28 lks., with blaze healed. (OBT)

A Fir, 32" dia., bears S.10°W., 19 lks., an old BT, with blaze healed. I re-blazed & re-marked this tree 1/4 S9 BT.

A Fir, 22" dia., bears N.41°W., 76 lks., mkd: 1/4 S4 BT. (New BT)

BLM remonumentation of certain orig. corner points by Wm. W. Glenn & James E. Jelley, Cadastral Surveyors, under group #s 350 & 635, surveyed April/May 1967 - (DCSO records C.S. File 65/27-1)

The 1/4 sec. cor. of secs. 4 & 9 monumented with an iron post, 1" dia., firmly set, projecting 10" above ground, with (properly mkd) brass cap, from which the OBTs:

A root hole, bears North 28 lks., with a down cedar alongside, 45" dia., with healed blaze.

A Fir, 45" dia., bears S.10°W., 19 lks., with healed blaze.

and a BT mkd. in 1945

A Fir, 39" dia., bears N.41°W., 76 lks., with healed blaze.

Set a 6 ft. steel fence post alongside the iron post.

continued next page

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 4 & 9

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Douglas Co. Surveyors Office - Stephen J. Flause, Deputy -
Karen Mosley - April 13, 1981 - C.S. File 61/19-37

Found - 1945 GLO brass cap properly mkd. on a 1"x30" IP
lying loose on ground surface. A red painted
steel fence post nearby protrudes 42" from
ground; a check of the bearing & distance to
orig. SW BT reveals that fencepost does not mark
corner position.

Accessories bearings & distances are check from corner
position as determined from SW BT.

An orig. Fir, 16" now 42" DBH D.Fir bears S.10°W.,
12.5 ft. Tree is opened to search for 1945
rescribing. Blaze found is opened to see scribing
¼.

An orig. Cedar, 28" is now a downed Cedar 50".
Center of uproot hole agrees reasonably well with
record bearing & distance. This Cedar has fallen
with blaze marks hidden.

A 22" Fir, now a 32" 8 ft. long tipped out stump has
uproot hole which agrees reasonable well with
record bearing & distance. This Fir stump also
has tipped over on its face & and no blaze marks
are found. (1945)

Set - Because of good condition of orig. SW BT, the GLO
brass cap monument is set the record bearing &
distance from this tree. WE ADD reset marks to
cap: US General Land Office Survey RESET ¼ S4 S9
DCSO 1981 1945" Cap protrudes 1" from ground. Red
fence post is set on south side of cap and
protrudes 44" from ground.

A 12" DBH D.Fir bears N.53°W., 38.1 ft. and is
scribed ¼ S4 CS BT on a double blaze.

A 7" DBH D.Fir bears N.24¼°W., 13.9 ft. & is scribed
¼ S4 CS BT as a bark scribe.

The new BTs and the orig. SW BT are tagged with DCSO BT tags.

Dependent resurvey by Edith M Forkner, Cadastral Surveyor,
under Group #2285, surveyed Aug. 2009/ Feb. 2010 (DCSO
records BLM plat 2011 & Vol. 56 Page(s) 22263-65)

The ¼ sec. cor. of secs. 4 & 9, remonumented by Price & Rigby
in 1945, utilized by Glenn, et al., in 1967, found lying
loose and reset by Flause, with the 1945 GLO monument in
1981; monumented with on iron post, 1" dia., firmly set,
projecting 1" above ground. with a brass cap (properly) mkd.
from which the remains of the original bearing trees

continued next page

TOWNSHIP 21 RANGE 08 POINT IDENTIFIER # 340600

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 4 & 9

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

A roothole bears North, 18.5 ft., alongside of which is a down cedar, 45" dia., no marks visible.
A fir, 56" dia., bears S.10°W., 12.5 ft., with axe marks visible on open decayed blaze.
and the remains of a BT mkd. by Price and Rigby
A roothole bears N.41°W., 50.2 ft., downhill of which is a fir rootwad, no marks visible.
and the BTs mkd. by Flauser
A fir, 28" dia., bears N.51½°W., 37.4 ft., with a healed blaze.
A hemlock, 19" dia. bears N.22°W., 14.0 ft. with scribe marks ¼ & other illegible scribe marks visible on bark.
A steel fence post is alongside the cor.
Corner is located W., 40 ft. from Blind Creek, 6 ft. wide, course N., on the W. side of bottom land, 30 ft. wide.