

PRIMARY CORNER DESCRIPTION So. Sec. cor. for 33 & 34 only

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Douglas Co. Surveyors Office, Gary L. Langlitz, Deputy -
Clell E. Goodwin; M. Lenora Ladig; A. Vic Cangie, crew - Aug.
7, 1975 - C.S. File 57/34-13

Found - Remains of one BT marked in 1945 BLM resurvey, a
fragmented, rotten Hemlock stump bearing
N.45°45'W., 57.4 ft. with scribing "W S33 BT"
visible.

The brass cap set in 1945 and all other corner
accessories have been destroyed.

Due to extremely steep slopes, shallow soil and loose rock,
it is impracticable to set any type of permanent monument. We
do however place a steel fence post at the corner point.

We mark the following new BTs:

An 8" Red Alder bears N.55°W., 34.7 ft. scribed
"T21S R8W S33 CS BT" on a double blaze.

A 7" D.Fir bears N.51°E., 23.6 ft. scribed "T21S R8W
S34 CS BT" on double blaze.

Les Roberts - Feb. 10, 1997 - M 124-44 & C.S. 65/12-5 A&B

Mon. Set - "PK" Nail in steep rock face using data of record
from 1975 Douglas Co. survey see C.S. 57/34.

Bt's Fd. - 12" Alder, N.55°W., 34.7' (scribe visible) 1975
BT.

16" Fir, N.51°E., 23.6' (scar vis.), 1975 B.T.

Douglas County Surveyors Office - Randall Smith & Stephen
Flause - Mar. 17, 1997 - C.S. 64/74-1

Found - BC/IP not found (1945) metal fence post found out of
ground.

Alum. nail per M124-44

26" now rotted down Hemlock, indeterminable size no
scribing visible, bears N.46 3/4°W., 57.4' agrees
with rec.) 1945

8" now 10" dia. Red Alder, with a partially healed
double blaze illegible scribing visible, bears
N.55°W., 34.7' (agrees with rec.) 1975

7" now 16" dia. D.Fir, with a fully healed double
blaze, bears N.51°E., 22.3' (rec. N.51°E., 23.6'
dist. fits a slope measurement) 1975

Position of Aluminum nail is referenced, a small ledge is
chiseled out and a 2" dia. brass disk is cemented onto sand
stone ledge at position of referenced nail.

New Bts- 16" dia. D.Fir double blazed and scribed T21S R8W
S34 CS BT", bears N.2½°E., 35.3'.

(Cont. Next Page)

TOWNSHIP 21 RANGE 08 POINT IDENTIFIER # 400100

PRIMARY CORNER DESCRIPTION So. Sec. Cor. for 33 & 34 only

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

11" dia. D.Fir double blazed and scribed T21S R8W
S33 CS BT", bears N.76°W., 8.3'.
Corner lies on a steep north slope (sand stone shallow soil)

BLM dependent resurvey by Aaron M Graham, Cadastral Surveyor,
under Group 1910, surveyed June/July 1999. (DCSO recs. Vol.
53 Page(s) 20488-9)

Beginning at the corner of secs. 33 & 34, only on the S. bdy.
of the Tp., perpetuated by Langlitz, Deputy County Surveyor
in 1975, from original evidence no longer in existence,
utilized by Roberts, in 1997, and further perpetuated by
Ware, County Surveyor in 1997; monumented with a brass disk,
loosely set, in a drill hole, with brass disk mkd.

D C S O
T 21 S R 8 W
S 33 | S 34
T 22 S
1997

from which bearing trees mkd. by Langlitz

A fir, 17" diam., bears N.53 3/4°E., 21.8 ft., with a
healed double blaze.

An alder, 12" diam., bears N.56 1/2°W., 34.4 ft., with illegible
scribe marks visible on a partially healed double blaze.
and the remains of bearing trees mkd. by Ware

A fir, 16" diam., bears N.4 1/2°E., 35.0 ft., with a healed
blaze.

A root hole, bears N.65 1/2°W., 7.7 ft., with a down fir
alongside, 11" diam., with a healed blaze.

Remove the Douglas County brass disk and discard.

At the corner point

Set a brass tablet, 3 1/4" diam., 3 1/2" stem, in drill hole, in
solid rock, with top mkd.

T 21 S R 8 W
S 33 | S 34
S 3
T 22 S
1999

Greg Lang - Jan. 2005 - C.S. File 65/54-1

Found - Brass Cap and Bearing Trees;

A 9 1/2" Alder bears N.56 1/2°W., 34.50' (N.56 1/2°W., 34.4'
per 1999 renewal)

A 19" D.Fir bears N.3 3/4°E., 35.10' (N.4 1/2°E., 35.0'
per 1999 renewal)

An 18" D.Fir bears N.53 3/4°E., 21.70' (N.53 3/4°E. 21.8'
per 1999 renewal)

continued next page

TOWNSHIP 21 RANGE 08 POINT IDENTIFIER # 400100

PRIMARY CORNER DESCRIPTION So. Sec. Cor. 33 & 34 only

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

New - A 9½" D. Fir bears S.3°E., 23.20' scribed "BT"
Note - Corner is located on a steep northerly slope; it is
easterly of and very near a ravine which is
tributary to Cedar creek.

Fd. BC & 4 BTs, by Ron Rice, 7/20/2013 - C.S. File 65/80-2 &
(C.S. File 65/81-11 Filed 4/24/2014)