

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 27 & 34

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Wm. P. Wright, Deputy Surveyor, under contract #486, dated Aug. 1, 1883 - (DCSO recs. Vol. 2 Page(s) 857-8)

-----  
Set post 4" dia., 4 ft. long with marked stone 12" in ground for 1/4 sec. cor. marked 1/4 S on N face from which:

Fir, 5" dia., bears N.85°W., 10 lks., mkd: 1/4 S BT.

Fir, 5" dia., bears S.85°W., 12 lks., mkd: 1/4 S BT.

BLM dependent resurvey by Marvin J. Lytle, Palmer Norseth, Thomas A. Tillman, Raymond M. Bicknell, Joseph S. Gawron, and Hans W. Thielsen, Cadastral Engineers, under Group #304, Surveyed Aug. 1952 thru Oct. 1954 - (DCSO recs. Vol. 30 Page(s) 12571)

-----  
Point for the 1/4 sec. cor. of secs. 27 & 34, at proportionate distance; there is no remaining evidence of the orig. corner. Set an iron post, 3 ft. long, 1" dia., 26" in the ground with brass cap marked:

1/4  $\frac{S\ 27}{S\ 34}$   
1952

from which

A Fir, 56" dia., bears N.65°45'E., 307 lks., mkd: 1/4 S27 BT

A Fir, 62" dia., bears S.54 1/4°E., 410 lks., mkd: 1/4 S34 BT.

John M. Phillips - For: Snellstrom Lumber - Aug. 20, 1959 - C.S. File 51/37

-----  
Done at the request of BLM

Found - Brass capped iron pipe marked 1/4 S27/S34 at approximately the location it was before being disturbed by tractor operations. It was pulled loose from the ground & the pipe was bent.

I obtained resurvey notes from BLM as follows:

56", Fir, bears N.65°45'E., 307 lks., mkd: 1/4 S27 BT

62", Fir, bears S.54 1/4°E., 410 lks., mkd: 1/4 S34 BT.

I found the 56" Fir and a hole on the edge of the road where the 62" Fir apparently used to be. It is now a windfall and has been bucked. I reset the pipe from the 56" Fir. This location tallies with the orig. location I remember before the logging commenced.

Note - See sketch of corner location in file.

continued next page

TOWNSHIP 21 RANGE 08 POINT IDENTIFIER # 440200

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 27 & 34

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

BLM remonumentation by Aaron M. Graham, Cadastral Surveyor under Group #1000, surveyed May 1999/April 2000 - (DCSO rec. Vol. 54 Page(s) 20743)

-----

The ¼ sec. cor. of secs. 27 & 34, monumented with an iron post, 1 in. dia., firmly set, projecting 6" above the ground, with brass cap (properly) mkd.

from which a bearing tree mkd. by Lytle, et. all

A fir, 57" dia., bears N.65¾°E., 202.6 ft., with a healed blaze.

and new bearing tree

A fir, 18" dia., bears S.42¾°E., 23.5 ft., mkd. ¼ S34 BT.