

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 1; S. 6, T21-7

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Laban H. Wheeler, Under Contract #467 dated April 7, 1883 (DCSO records Vol. 2 Page(s) 563)

-----  
Set post 3" dia., 4 ft. long, 24" in ground for qr. sec. cor., mkd. ¼ S on W. face, from which

A Fir 5" dia., bears N.31°E., 5 lks. dist. mkd. ¼ S BT.

A Fir 10" dia., bears S.55°W., 41 lks. dist. mkd. ¼ S BT

BLM Resurvey by Lytle; Norseth; Tillman; Bicknell; Gawron and Thielsen, Cadastral Engineers, under Group #304, Surveyed Aug. 1952/Oct. 1954 - (DCSO records Vol. 30 Page(s) 12555-56)

-----  
The ¼ sec. cor., determined from the remaining original bearing tree, as follows:

A solid Fir snag, 26" dia., bears S.55°W., 41 lks. dist., with blaze healed; I open blaze and uncover scribe marks ¼ S.

At the corner point

Set an iron post, 3 ft. long, 1" dia., 28" in the ground, with brass cap mkd:

¼  
S 1 | S 6  
1954

from which new bearing trees:

A Fir 30" dia., bears N.77°E., 38 lks. dist. mkd. ¼ S6 BT.

A Fir 23" dia., bears S.26¼°W., 47 lks. dist. mkd. ¼ S1 BT

BLM remonumentation of certain orig. corner points by Wm. W. Glenn & James E. Jelley, Cadastral Surveyors, under group #s 350 & 635, surveyed April/May 1967 - (DCSO records C.S. File 65/27-1)

-----  
The ¼ sec. cor. of secs. 1 & 6 on the E. bdy. of the Tp., monumented with an iron post, 1" dia., firmly set, projecting 4" above ground, with brass cap (properly mkd) from which the remaining OBT

A sawed Fir stump, 40" dia., bears S.55°W., 41 lks., no marks visible on decayed blaze.

and BTs mkd. in 1954

A Fir snag, 32" dia., bears N.77°E., 38 lks., with fragmentary scribe marks visible on open and decayed blaze.

A Fir, 25" dia., bears S.26¼°W., 47 lks., with scribe marks ¼ visible on open blaze.

and a new BT

A Fir, 35" dia., bears N.7°E., 80½ lks., mkd: ¼ S6 BT.

Set a 6 ft. steel fence post alongside the iron post.

continued next page

TOWNSHIP 21 RANGE 08 POINT IDENTIFIER # 700640

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 1; S. 6, T21-7

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Ronald L. Rice - For: Oxbow Timber 1 LLC - May 2014 - C.S.  
File 65/84-4

-----

Found - 1954 GLO Brass cap with the following accessories:  
40" Fir stump bears S.55°W., 27.1' - rotted face  
32" Fir stump bears N.77°E., 25.1' - no marks  
35" Fir bears S.26¼°W., 31.0' - healed face  
46" Fir bears N.70°E., 53.1' - healed face  
New BTs- 59" D.Fir bears N.31°W., 36.1' - blazed, scribed ¼ S1  
BT  
30" D.Fir bears S.1°E., 40.4' - blazed, scribed ¼ S6  
BT  
Steel post adjacent to corner