

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Alonzo Gesner, Deputy Surveyor, under Contract #608 -dated April 17, 1893 - (DCSO records Vol. 2 Page(s) 909)

Set Alder post 4½ ft. long, 5" sq., 24" in the ground on steep hill side, sloping NE. for ¼ sec. cor. marked ¼ S on the W. face, from which
A Fir 72" dia, bears S.14°E., 45 lks. dist. mkd. ¼ S BT
A Fir 36" dia., bears N.60°W., 66 lks. dist. mkd. ¼ S BT

GLO resurvey by Fred Mensch, Charles M. Collier and Fred W. Rodolf, U.S. Cadastral Engineers; Elmer F. Strickler, U.S. Surveyor, and Gerald A. Sorrels, U.S. Transitman, under Instructions dated April 24, 1917 (surveyed 1919) - (DCSO records Vol. 3 Page(s) 999) and (Dup. Pg. 1034-35)

(7.33 chs.)
Intersect the point for the old ¼ sec. cor., located by reference to the old bearing trees, which are marked as described by the surveyor general. I now destroy all evidence of this cor. and continue my line.
(40.00 chs., N.0°27'W)
Set an iron post 3 ft. long, 1" dia., 26" in the ground for ¼ sec. cor. of sec. 1 only, with brass cap mkd. ¼
S 1 |
1919
from which
A Fir 14" dia., bears S.67°W., 35 lks. dist. mkd. ¼ S1 BT.
A Fir 11" dia., bears N.10°W., 22 lks. dist. mkd. ¼ S1 BT.

Douglas Co. Surveyors Office - L.E. Monrean, Deputy - Wit: S.J. Flause; K.S. Mosley - April 2, 1981 - C.S. File 61/19-25

Found - 3/4" inside dia. concrete filled iron pipe, badly rusted with brass cap stamped "¼ S1 1919". Monument is broken into 3 pieces with lower portion remaining firmly set, protruding 3" above ground.
1919 BT, a 14" D.Fir now a 30" stump, 36" high, bears S.67°W., 22.1 ft. (Rec. 23.1 ft. checks slope measurement.) We open portion of blaze and find scribing "¼"
1919 BT, an 11" D.Fir now a 14" stump, 14" high, bears N.78°W., 13.8 ft. (Rec. N.10°W., 14.5 ft.) We open blaze and find scribing "BT." The only logical determination we can make at this time, is that the compass bearing of N.80°W., (being

(Cont. Next Page)

TOWNSHIP 21 RANGE 09 POINT IDENTIFIER # 100652

PRIMARY CORNER DESCRIPTION E. 1/4 Cor. for Sec. 1 only, T21-10

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

10° off of cardinal West) was possibly misread. As the stump is leaning, a bearing of N.80°W., a distance of 14.5 ft. would be reasonable course to center of tree at blaze height. The blaze and scribing faces monument position. No evidence of tree was found at record bearing and distance. Set a 1" x 30" Iron pipe with attached brass cap stamped: "Douglas County Surveyor T21S R10W S1 ¼ 1981", is set at corner position. Monument is set with cap 4" above ground. Placed pieces of old monument along N. and S. side underground.

New Accessories:

- Set boat spike stamped "BO 1" in pitch ring of 30" D.Fir stump, bears S.67°W., 23.1 ft. (1919 BT)
- Set boat spike stamped "BO 2" in pitch ring of 14" D.Fir stump, bears N.78°W., 14.1 ft. (1919 BT)
- Set boat spike stamped "BO 3" in pitch ring of 16" dia. 16" high D.Fir stump, bears N.48°W., 19.0 ft.
- A D.Fir 14" double blazed and scribed "¼ S1 CS BT", bears N.15°W., 26.9 ft.

All bearing objects are tagged. Corner lies about 25 ft. S. of cutting line running along ridge top E-W.