

PRIMARY CORNER DESCRIPTION So. sec. cor. for 31 and 32 only

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by Alonzo Gesner, Deputy Surveyor, under Contract #608 -dated April 17, 1893 - (DCSO records Vol. 2 Page(s) 900)

-----  
Set Fir post, 4½ ft. long, 4" sq., 24" in the ground on hill side sloping SW. for cor. to secs. 31, 32, 5 and 6. Marked T21S S32 on the NE.; R9W S5 on the SE.; T22S S6 on the SW.; and S31 on the NW. faces with 5 notches on the E. and 1 notch on the W. edges, from which

A Fir 6" dia., bears N.17°30'E., 157 lks. dist. mkd. T21S R9W S32 BT.

A Fir 30" dia., bears S.73°E., 195 lks. dist. mkd. T22S R9W S5 BT.

A D.Fir stump 20" dia., bears S.74°W., 54 lks. dist. mkd. T22S R9W S6 BT.

A Fir 30" dia., bears N.81°W., 257 lks. dist. mkd. T21S R9W S31 BT.

GLO survey by Elmer O. Worrick, Deputy Surveyor, under Contract #632, dated April 28, 1894 - (DCSO records Vol. 4 Page(s) 1681-82)

-----  
Intersected N. bdy. of T., 314 lks. West of the corner to secs. 31 and 32, T21S, which is a post 2 ft. above ground, 4" sq., mkd. T21S S32 on the NE.; R9W S5 on the SE.; T22S S6 on the SW.; S31 on the NW. faces, with 5 notches on the E. and 1 notch on the W. edges, from which

A Fir 8" dia., bears N.17°30'E., 157 lks. dist. mkd. T21S R9W S32 BT.

A Fir 30" dia., bears S.17°30E., 195 lks. dist. mkd. T21S R9W S5 BT.

A stump 20" dia., bears S.44°W., 54 lks. dist. mkd. T22S R9W S6 BT.

A Fir 30" dia., bears N.81°W., 257 lks. dist. mkd. T21S R9W S31 BT.

I destroyed marks on post and BT on S.

Douglas Co. Surveyors Office - John M. Powell, J. Heritage, W. Penley, crew - Sept. 29, 1971 - C.S. File 53/66-126

-----  
Found - 8" Fir N.17½°E., 103.6 ft. This tree opened years ago and rotten.

30" Fir S.73°E., 128.7 ft. This tree destroyed in 1894.

I do not find NW. BT.

Using these two trees, call on top of ridge of 42.9 ft. and coming 207.2 ft. East from closing cor. of 5 & 6,

(Cont. Next Page)

TOWNSHIP 21 RANGE 09 POINT IDENTIFIER # 200100

PRIMARY CORNER DESCRIPTION So. sec. cor. for 31 & 32 only

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

I Set brass cap at sec. cor. mkd: County Surveyors Office  
T 21 S R 9 W  
S 31 | S 32  
S 5  
T 22 S  
1971  
New BTs -22" D.Fir N.83°E., 22.1 ft. scribed T21S R9W S32 CS  
BT.  
22" D.Fir N.13°W., 24.7 ft. scribed T21S R9W S31 CS  
BT.  
10" D.Fir S.21°E., 15.0 ft. scribed S5 CS BT.

Cor. fd. and used in BLM survey by Wofford, Rogers and Chatters, under Group #'s 811 and 1000, surveyed Aug. 1973/Oct. 1979 (DCSO records, Vol. 40 Page 16029)

Corner tied and used in BLM survey by Malloy and Farnsworth, under Group #'s 1125 and 1226, surveyed Nov/Dec. 1982 (DCSO records, Vol. 47 Pages 17933-34)

BLM resurvey by Joel E. Robb, Cadastral Surveyor, under Group #1281, surveyed Aug/Oct. 1985 - (DCSO records Vol. 48 Page(s) 18190)

-----

CORNER REPORT

The cor. of secs. 31 and 32 only, monumented with an iron post, 1¼" dia., firmly set, projecting 4" above ground with a 1971 county brass cap, from which the remaining original bearing tree:

A Fir 56" dia., bears S.73°E., 195 lks. dist. with healed blaze.

and bearing trees mkd. by Powell in 1971:

A Fir 22" dia., bears N.83°E., 33½ lks. dist. with healed blaze.

A Fir 11" dia., bears S.21°E., 23 lks. dist. with healed blaze.

A Fir 22" dia., bears N.14½°W., 36½ lks. dist. with healed blaze. (Rec. N.13°W., 37½ lks.)