

PRIMARY CORNER DESCRIPTION Cor Secs 29, 30, 31, & 32

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Alonzo Gesner, Deputy Surveyor, under Contract #608, dated April 17, 1893 - (DCSO rec. Vol. 2 Page(s) 967)

Set Fir post 4½ ft. long, 4" sq., 24" in the ground on hill side sloping SE for cor. to secs. 29, 30, 31 & 32. Marked T21S S29 on the NE, R9W S32 on the SE, S31 on the SW & S30 on the NW, faces with 1 notch on the S & 5 notches on the E edges, from which

- A Fir, 24" dia., bears N.17°E., 88 lks., mkd: T21S R9W S29 BT.
- A Fir, 16" dia., bears S.78°E., 49 lks., mkd: T21S R9W S32 BT.
- A Fir, 6" dia., bears S.40°W., 5 lks., mkd: T21S R9W S31 BT.
- A fir, 10" dia., bears N.19°W., 24 lks., mkd: T21S R9W S30 BT.

BLM dependent resurvey by Peter A. Peterson, Cadastral Surveyor, under Group #350 & 511, surveyed April 1966/May 1967 - (DCSO records, Vol. 34 Page(s) 14265)

The cor. of secs. 29, 30, 31, & 32, determined at record bearing & distance from the orig. BTs:

- A Fir, 42" dia., bears N.17°E., 88 lks., with healed blaze.
- A Fir stump hole, bears S.40°W., 5 lks.
- A Fir, 32" dia., bears N.19°W., 24 lks., with healed blaze.

At the corner point

Set a fiberglass post, 28" long, 2½" dia., 24" in the ground, with brass cap marked:

T 21 S	R 9 W
<u>S 30</u>	<u>S 29</u>
S 31	S 32
1967	

from which new BTs

- A Hemlock, 6" dia., bears S.60°E., 132 lks., mkd: T21S R9W S32 BT.
- A Cedar, 6" dia., bears S.84°W., 65 lks., mkd: T21S R9W S31 BT.

Douglas Co. Surveyors Office - John Powell - W. Penley - J. Heritage - Sept. 30, 1971 - C.S. File 53/66-123

Found - 1967 BLM brass cap properly mkd.
42" D.Fir, now 50" N.17°E., 58.1 ft. Show scar.
6" Cedar, now 7", S.84°W., 42.9 ft. T21S R9W S31 BT.
continued next page

TOWNSHIP 21 RANGE 09 POINT IDENTIFIER # 200200

PRIMARY CORNER DESCRIPTION Cor Secs 29, 30, 31, & 32

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

32" D.Fir, now 40" N.19°W., 15.8 ft. Shows old scar.
New BTs- 12" Cedar, S.14½°E., 51.4 ft. scribed T21S R9W S32
CS BT.
24" Cedar, N.39°W., 26.4 ft. scribed T21S R9W S30 CS
BT.
Note - Area to the south has been logged.

Fd. Ok 12/26/1989 by L. Roberts - M 109-42

BLM Dependent resurvey by Joseph M. Mannix, Cadastral Surveyor under Group No. 2721, surveyed June/Aug. 2013 - (DCSO records Vol. 58 Page(s) 23171)

The cor. of secs. 29, 30, 31, and 32, perpetuated by the Douglas County Surveyor's Office, in 1991; monumented with an iron post, 2½" dia., firmly set, projecting 4" above ground, with a brass cap (properly) mkd. from which the remains of the original bearing trees
A decayed fir stump, size indeterminate, bears N.17°E., 58.1 ft., with a healed blaze.
A decayed fir stump, 40" dia., bears N.19°W., 15.8 ft., with a healed decayed blaze with a sheet metal cap.
and the bearing trees mkd. by Peterson in 1966-67
A hemlock, 27" dia., bears S.60°E., 87.1 ft., with a healed blaze.
A cedar, 28" dia., bears S.84°W., 42.9 ft., with a healed blaze.
and the BTs mkd. by the Douglas County Surveyor's Office
A cedar, 39" dia., bears S.14¾°E., 51.4 ft., with a healed blaze.
A cedar, 37" dia., bears N.40¼°W., 26.4 ft., with a healed blaze.
and a new bearing tree
A hemlock, 20" dia., bears N.52¼°E., 29.7 ft., mkd. T21S R9W S29 BT and a Mag Nail driven at the base on left side center.
Alongside the cor. is an aluminum fence post.
NAD 1983 (2011)
Latitude: 43°42'26.40"N. Longitude: 123°48'15.40"W.