

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 5; & 32, T20-9

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO Survey by Wm. Thiel under Contract #260 dated April 17, 1877 - (DCSO records Vol. 1 Page(s) 304)

Set a Chittem post for 1/4 sec. cor. bet. secs. 32 and 5; from which

A Maple 24" dia., bears S.62 1/4°E., 88 lks. dist.

A Fir 36" dia., bears N.64°E., 55 lks. dist.

GLO survey by Alonzo Gesner, Deputy Surveyor, under Contract #608 -dated April 17, 1893 - (DCSO records Vol. 1 Page(s) 365-66)

The 1/4 sec. cor., which is a post, 2 ft. above ground, 3" sq., mkd. 1/4 S on the N. face; from which

A Fir, stump, 36" dia., bears N.64°E., 55 lks. dist. mkd. 1/4 S BT.

A Maple 24" dia., bears S.62°15'E., 90 lks. dist. mkd. 1/4 S BT.

BLM Resurvey by Thomas A. Tillman and Joseph S. Gawron, Cadastral Engineers, under Group #306, surveyed May 1953/Oct. 1954 - (DCSO records Vol. 29 Page(s) 12448)

The 1/4 sec. cor., determined from the original bearing trees, as follows:

A Fir 60" dia., bears N.64°E., 55 lks. dist., I uncover partial scribe marks of proper age at edge of old burned blaze. (Gesner reported this tree as a stump.)

A double Maple 40" dia., bears S.62 1/4°E., 183 lks. dist. bearing a healed blaze, which I open, but face of blaze at proper age is destroyed. (Thiel record, 88 lks.; Gesner, 90 lks. dist.)

At the corner point

Set an iron post, 3 ft. long, 1" dia., 28" in the ground, with brass cap mkd:

1/4 $\frac{S\ 32}{S\ 5}$
1953

from which new bearing trees:

A Fir 24" dia., bears N.3 1/2°E., 51 lks. dist. mkd. 1/4 S32 BT.

A Fir 24" dia., bears S.84°W., 20 lks. dist. mkd. 1/4 S5 BT.

From this point, a Fir 16" dia., bears N.39°E., 26 lks. dist., with partially healed blazes on N., S., E., and W. sides.

Cor. is located at edge of bottom, bears N. and SE.

Fd. OK, Aug. 1981 by W. Eimsted - M 89-13