

PRIMARY CORNER DESCRIPTION So. 1/4 Cor. Sec. 33 only

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by Alonzo Gesner, Deputy Surveyor, under Contract #608 -dated April 17, 1893 - (DCSO records Vol. 2 Page(s) 898)

Set Maple post, 5 ft. long, 4" sq., 24" in the ground on hill side sloping SE for ¼ sec. cor., marked ¼ S on the N. face, from which
A Fir 34" dia., bears N.8°30'E., 16 lks., mkd. ¼ S BT
A Hemlock 24" dia., bears S.15°30'E., 50 lks., mkd. ¼ S BT

V. W. Hosford - For: Evans Products Co. - C.S. File 41/292 and M 10-80 - August 1954

I find the South ¼ S 33. At this corner I found a 3/4" Iron pipe with cap marked ¼ S33. Original BT for section 33 is a stump with overgrown scar. Original BT for section 4 is a 30" dead Hemlock with burned scar.

Douglas County Surveyors Office - John M. Powell - C.S. File 53/66-135 - Sept. 1971

Corner searched for, not found. Found survey target and hub approx. 11 chains West of ¼ cor. 33, T21S R9W.

Dependent resurvey by Boyd W. Peterson & John A. Farmer, Cadastral Surveyors, under Group #1791, surveyed Oct. 1995/Feb. 1998. (DCSO records Vol. 52 Page(s) 19858)

The ¼ sec. cor. of secs. 33 only, perpetuated by Hosford, in 1954, recorded in the Douglas County Courthouse file No. 41/292 & plat No. M 10-80; monumented with an iron pipe, 1½" diam., firmly set, projecting 12" above the ground, from which the remains of an original bearing tree:

A fir stump, 47" diam., bears N.8½°E., 16 lks., no marks visible.

At the corner point

Set a stainless steel post, 28 ins. long, 2 ½ ins. diam., 22 ins. in the ground, with brass cap mkd.

T21S R9W
¼ S 33
T22S
1996

from which new bearing trees

A fir, 5" diam., bears N.28½°E., 31½ lks., mkd. X BT.

A fir, 10" diam., bears N.60°W., 17 lks., mkd. ¼ S33 BT.

Deposit the iron pipe and a magnet in a white plastic case at base of stainless steel post.