

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by Alonzo Gesner, Deputy Surveyor, under Contract #608, dated April 17, 1893 - (DCSO rec. Vol. 2 Page 960)

Set cedar post, 5 ft. long, 6" sq. 24" in the ground for 1/4 sec. cor. mkd. 1/4 S on the N face from which

A fir, 16" dia., bears S.7°E., 15 lks., mkd: 1/4 S BT.

A fir, 22" dia., bears N.23°W., 33 lks., mkd: 1/4 S BT.

Ron Quimby - For: Roseburg Resources Co. - Crew: N Fromdahl & L Heddens - 12/2019 - C.S. File 65/104-28

Found stake with axe work on 2 sides, other 2 sides have rotted away. Stake is slightly charred.

Found old flagging around stake in the ground, do not believe this to be original post as called for in orig. notes. Believe this to be placed by Timber Co. 40-50 years ago during logging operation.

Rotted stump and down rotted log fit the orig calls good. This point is only 3 ft ± of true line between sec. corners and is close to half way between section corners.

This point was set and used in prior logging.

I believe this is the best available evidence of the original corner location:

Found - Partial rotted cedar stake with axe work on 2 sides (other sides rotted) stake was still standing.

Found old red ribbon in ground around stake.

Rotted stump N.23°W., 21.8 ft. (rec. N.23°W., 21.8)

Down and rotted log remnant size not determined

S.7°E., 9.9 ft. (rec. S.7°E., 9.9 ft.)

New - Replaced stob with 5/8" IR with 2" alum cap stamped:

ROSEBURG RESOURCES COMPANY

T21S R9W

1/4 Δ $\frac{S\ 16}{S\ 21}$

LS 1654

2019

9" Fir N.87°E., 12.6 ft. scribed 1/4 S16 BT

23" Fir S.23°E., 31.6 ft. scribed 1/4 S21 BT

15" Fir S.10°W., 12.6 ft. scribed 1/4 S21 BT

7" Fir N.84°W., 8.3 ft. scribed 1/4 S16 BT.

Note - Compass decl. 15 1/2°E.