

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 27 & 28

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Alonzo Gesner, Deputy Surveyor, under Contract #608, dated April 17, 1893 - (DCSO rec. Vol. 2 Page(s) 943)

Set Hemlock post, 5 ft. long, 5" sq., 24" in the ground for 1/4 sec. cor., mkd: 1/4 S on the W face; from which

A Hemlock, 24" dia., bears S.65°E., 35 lks., mkd: 1/4 S BT.

A Fir, 24" dia., bears S.70°W., 61 lks., mkd: 1/4 S BT.

BLM dependent resurvey by Peter A. Peterson, Cadastral Surveyor, under Group #350 & 511, surveyed April 1966/May 1967 - (DCSO records, Vol. 34 Page(s) 14264)

The 1/4 sec. cor. of secs. 27 & 28, perpetuated by person(s) unknown with an iron pipe, 60" long, 2" dia., extending 30" above ground, firmly set, from which the orig. BTs:

A sawed Hemlock stump, 18" dia., bears S.65°E., 35 lks., with no marks remaining.

A sawed Fir stump, 40" dia., bears S.70°w., 60 lks., with scribe marks S visible on opened blaze.

At the corner point

Set an iron post, 28" long, 2 1/2" dia., 24" in the ground, with brass cap marked:

1/4
S 28 S 27
T21S R9W
1967

from which new BTs

A Fir, 6" dia., bears N.42°E., 90 lks., mkd: 1/4 S27 BT.

A Fir, 5" dia., bears S.10°W., 32 1/2 lks. mkd: 1/4 S28 BT.

Deposit the iron pipe alongside the iron post.

Douglas Co. Surveyors Office - John M. Powell -May 24, 1971 - C.S. File 53/66-9

Form letter 9184.2 Coos Bay!

Found - BLM brass cap mkd:

1/4
S28/S27
T21SR9W
1967

Also 1 1/2" iron pipe.

Both 1967 BTs ok & tagged.

As noted corner lies about 100' East of road. I cut trees & ribbon line on rd. No other marks.

Fd. Ok by D. Edwards, June 2000 - M 135-6

continued next page

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 27 & 28

Alias	Description

BLM Dependent resurvey by Joseph M. Mannix, Cadastral Surveyor under Group No. 2721, surveyed June/Aug. 2013 - (DCSO records Vol. 58 Page(s) 23170)

The ¼ sec. cor. of secs. 27 and 28, monumented with an iron post, 2½" dia., firmly set, projecting 14" above ground, with a brass cap (properly) mkd.

from which the remains of an original bearing tree

A decayed fir stump, 31" dia., bears S.70°W., 40.3 ft. with scribe marks ¼ S visible on open decayed blaze.

and the remains of the BTs mkd. by Peterson in 1966-67

A fir, 28" dia., bears N.39¾°E., 59.4 ft., with a healed blaze. (Record, N.42°E.)

A fir stump, 24" dia., bears S.10°W., 21.5 ft., with a healed blaze.

and a new bearing tree

A hemlock, 16" dia., bears S.22½°E., 14.5 ft., mkd. ¼ S27 BT.

No suitable trees in sec. 28.

Alongside the cor. is an aluminum fence post and an iron pipe, lying loose, 60 ins. long, 2" dia. Remove the iron pipe from the area.

From the corner, S.0°38'09"W.,

130 ft., graveled road, 10 ft. wide, bears N.30°W. and S.35°E.

215 ft., ridge, bears N.35°W. and S.35°E.

A search was made for all original line trees along the South 1/2 mile bet. secs. 27 and 28 and none were recovered.

NAD 1983 (2011)

Latitude: 43°42'52.98"N. Longitude: 123°45'52.06"W.