

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 3 & 10

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

GLO survey by Alonzo Gesner, Deputy Surveyor, under Contract #608, dated April 17, 1893 - (DCSO rec. Vol. 2 Page(s) 951)

Set alder post, 5 ft. long, 4" sq. 24" in the ground on hill side sloping NE for 1/4 sec. cor. mkd. 1/4 S on the N face, from which

 A Cedar 10, bears S.15°E., 46 lks., mkd: 1/4 S BT.

 A Fir, 40" dia., bears N.49°E., 16 lks., mkd: 1/4 S BT.

BLM dependent resurvey by Peter A. Peterson, Cadastral Surveyor, under Group #350 & 511, surveyed April 1966/May 1967 - (DCSO records, Vol. 34 Page(s) 14245)

The 1/4 sec. cor. of secs. 3 & 10 determined at the record bearing & distance from the orig. BTs:

 A Fir, 65" dia., bears N.49°E., 16 lks., with healed blaze.

 A Cedar, 18" dia., bears S.15°E., 46 lks., with no marks visible on partially opened blaze.

At the corner point

Set an iron post, 28" long, 2 1/2" dia., 24" in the ground, with brass cap marked:

1/4 $\frac{S}{S 10}$

T 21 S R 9 W

1966

BLM Dependent resurvey by Joseph M. Mannix, Cadastral Surveyor under Group No. 2721, surveyed June/Aug. 2013 - (DCSO records Vol. 58 Page(s) 23170-1)

The 1/4 sec. cor. of secs. 3 and 10, perpetuated by person(s) unknown, monumented with an iron post, 2 1/2" dia., firmly set, projecting 1" above ground, with a brass cap (properly) mkd. from which the remains of the original bearing trees

 A fir, 90" dia., bears N.49°E., 10.6 ft., no marks visible.

 A decayed cedar stump, 21" dia., bears S.15°E., 30.4 ft., with a healed blaze.

and a bearing tree mkd. by person(s) unknown

 A hemlock, 27" dia., bears N.42°W., 46.3 ft., with a healed blaze & a spike at the base on right side center and a new bearing tree

 A fir, 9" dia., bears S.35 3/4°W., 18.8 ft., mkd. 1/4 S10 BT. Alongside the cor. is an aluminum fence post.

TOWNSHIP 21 RANGE 09 POINT IDENTIFIER # 440600

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 3 & 10

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Jerry Estabrook - For: Roseburg Resources Co. - 10++/2020 - M177-54

Found - A 2½" iron pipe with 3" brass cap marked "T21 S R9W
¼ S3 S10 1966" per 1966 BLM notes, Douglas CO.
Surveyor's record Vol. 34, pg 14245.

Set - Steel fence post alongside monument.

Fd BTs - A 76" Fir with healed face & tag bears N.49°E.,
10.6'.

A decayed cedar stump with no visible marks bears
S.15°E., 30.4'.

A 9" Fir with healed face and tag bears S.35°45'W.,
18.8'.

A 27" Hemlock with healed face & tag bears N.42°W.,
46.3'.

New BT - A 10" Alder, bark scribed "N¼ S10 BT" with X- chop
and tag bears S.2°W., 28.7' to a spike at side
center.

Lat. and Long. per GARMIN ETREX HAND HELD GPS
N: 43°45'49.9" W:123°45'16.8"